

الله
بِسْمِ اللّٰهِ الرَّحْمٰنِ الرَّحِيْمِ

فصل سوم

• بازرسی و ارزیابی جوش

مشخصات روش جوشکاری

Welding Procedure Specification

- WPS یا مشخصات روش جوشکاری، عبارت است از یک دستورالعمل به منظور فراهم کردن روش جوشکاری مطابق با ملزومات یک آیین نامه. WPS بایستی تمامی متغیرهای اساسی و غیر اساسی را برای هر فرآیند جوشکاری مشخص کند و هر وقت لازم باشد، متغیرهای تکمیلی برای هر فرآیند جوشکاری اعمال شود. معمولاً "مهندسین جوشکاری WPS را به شکل جدولی تهیه می کنند که در آن اطلاعات جزئی مربوط به شرایط جوشکاری برای کاربرد مورد نظر و با قابلیت تکرار و قابل اجرا توسط جوشکاری آموخته دیده، فراهم شده است. یک نمونه از فرم WPS در ضمیمه ارائه شده است

فرم استاندارد دستورالعمل جوشکاری WPS

شماره تجدیدنظر	تاریخ	توسط	نام شرکت.....				
تاریخ.....	شماره دستورالعمل.....				
<input checked="" type="checkbox"/> اتوماتیک		<input type="checkbox"/> نیمه اتوماتیک		روش جوشکاری.....			
						نوع درز	
جوش شیاری				<input type="checkbox"/> دو رو	<input checked="" type="checkbox"/> یک رو	نوع:	
جوشکاری قائم: سربالا		<input checked="" type="checkbox"/> سربالین		<input type="checkbox"/> خیر	<input checked="" type="checkbox"/> بله	پشت بند:	
خواص الکتریکی						مصالح پشت بند:	
نوع انتقال (GXAW):						ضخامت روشه:	
مدار گوتاه		<input type="checkbox"/> قطرهای				بازشدگی روشه:	
DCEN		<input checked="" type="checkbox"/> DCER				شاع.	
جریان:		<input type="checkbox"/> AC				زاویه شیار:	
غیره.....						شیارزی پشت: بله	
الکترود تنگستن (GTAW):						غیره	
الدازه						مشخصات فنی:	
نوع						نوع یا رده:	
تکنیک جوشکاری						ضخامت:	
<input checked="" type="checkbox"/> زنجیری		<input checked="" type="checkbox"/> زیکلر گ				صالح الکترود	
<input checked="" type="checkbox"/> یک پاسه		<input type="checkbox"/> چند پاسه				AWS مشخصات فنی	
تمدداد الکترود						AWS رده طبق	
فواصل الکترود: طولی						پوشش	
عرضی						نوع پودر:	
زاویه						گاز:	
فاصله بالطفعه کار						ترکیبها	
تعییزی میان پاس						نوع روکش الکترود	
صلبیات پس گرمابش						پیش گرمابش	
درجه حرارت						دهای پیش گرمابش، حداقل.....	
زمان						دهای میان پاس، حداقل.....	
						حدا کثر.....	
عبور	روشن جوشکاری	الکترود		جریان		mm/min سرعت حرکت	هنده سه درز
		د	رد	قطر	نوع و قطبیت		
۱							
۲							
۳							

Blank Sample WPS Form (GTAW & SMAW)
WELDING PROCEDURE SPECIFICATION (WPS)

Company Name				WPS No.	Rev. No.	Date																																																																																																																																																																																																																																																	
Authorized by		Date		Supporting PQR(s) CVN Report																																																																																																																																																																																																																																																			
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th>BASE METALS</th> <th>Specification</th> <th>Type or Grade</th> <th>AWS Group No.</th> </tr> <tr> <td>Base Material</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Welded To</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Backing Material</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Other</td> <td></td> <td></td> <td></td> </tr> </table>				BASE METALS	Specification	Type or Grade	AWS Group No.	Base Material				Welded To				Backing Material				Other				<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th>BASE METAL THICKNESS</th> <th>As-Welded</th> <th>With PWHT</th> </tr> <tr> <td>CJP Groove Welds</td> <td></td> <td></td> </tr> <tr> <td>CJP Groove w/CVN</td> <td></td> <td></td> </tr> <tr> <td>PJP Groove Welds</td> <td></td> <td></td> </tr> <tr> <td>Fillet Welds</td> <td></td> <td></td> </tr> <tr> <th>DIAMETER</th> <td></td> <td></td> </tr> </table>			BASE METAL THICKNESS	As-Welded	With PWHT	CJP Groove Welds			CJP Groove w/CVN			PJP Groove Welds			Fillet Welds			DIAMETER																																																																																																																																																																																																													
BASE METALS	Specification	Type or Grade	AWS Group No.																																																																																																																																																																																																																																																				
Base Material																																																																																																																																																																																																																																																							
Welded To																																																																																																																																																																																																																																																							
Backing Material																																																																																																																																																																																																																																																							
Other																																																																																																																																																																																																																																																							
BASE METAL THICKNESS	As-Welded	With PWHT																																																																																																																																																																																																																																																					
CJP Groove Welds																																																																																																																																																																																																																																																							
CJP Groove w/CVN																																																																																																																																																																																																																																																							
PJP Groove Welds																																																																																																																																																																																																																																																							
Fillet Welds																																																																																																																																																																																																																																																							
DIAMETER																																																																																																																																																																																																																																																							
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2">JOINT DETAILS</th> </tr> <tr> <td>Groove Type</td> <td></td> </tr> <tr> <td>Groove Angle</td> <td></td> </tr> <tr> <td>Root Opening</td> <td></td> </tr> <tr> <td>Root Face</td> <td></td> </tr> <tr> <td>Backgouging</td> <td></td> </tr> <tr> <td>Method</td> <td></td> </tr> </table>				JOINT DETAILS		Groove Type		Groove Angle		Root Opening		Root Face		Backgouging		Method		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2">JOINT DETAILS (Sketch)</th> </tr> <tr> <td colspan="2"></td> </tr> </table>			JOINT DETAILS (Sketch)																																																																																																																																																																																																																																		
JOINT DETAILS																																																																																																																																																																																																																																																							
Groove Type																																																																																																																																																																																																																																																							
Groove Angle																																																																																																																																																																																																																																																							
Root Opening																																																																																																																																																																																																																																																							
Root Face																																																																																																																																																																																																																																																							
Backgouging																																																																																																																																																																																																																																																							
Method																																																																																																																																																																																																																																																							
JOINT DETAILS (Sketch)																																																																																																																																																																																																																																																							
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2">POSTWELD HEAT TREATMENT</th> </tr> <tr> <td>Temperature</td> <td></td> </tr> <tr> <td>Time at Temperature</td> <td></td> </tr> <tr> <td>Other</td> <td></td> </tr> </table>				POSTWELD HEAT TREATMENT		Temperature		Time at Temperature		Other																																																																																																																																																																																																																																													
POSTWELD HEAT TREATMENT																																																																																																																																																																																																																																																							
Temperature																																																																																																																																																																																																																																																							
Time at Temperature																																																																																																																																																																																																																																																							
Other																																																																																																																																																																																																																																																							
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="7">PROCEDURE</th> </tr> <tr> <td>Weld Layer(s)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Weld Pass(es)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Process</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Type (Manual, Mechanized, etc.)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Position</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Vertical Progression</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Filler Metal (AWS Spec.)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>AWS Classification</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Diameter</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Manufacturer/Trade Name</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Shielding Gas Compos. (GTAW)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Flow Rate (GTAW)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Nozzle Size (GTAW)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Preheat Temperature</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Interpass Temperature</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Electrical Characteristics</td> <td>—</td> <td>—</td> <td>—</td> <td>—</td> <td>—</td> <td>—</td> </tr> <tr> <td>Electrode Diameter (GTAW)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Current Type & Polarity</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Amps</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Volts</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Cold or Hot Wire Feed (GTAW)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Travel Speed</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Maximum Heat Input</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Technique</td> <td>—</td> <td>—</td> <td>—</td> <td>—</td> <td>—</td> <td>—</td> </tr> <tr> <td>Stringer or Weave</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Multi or Single Pass (per side)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Oscillation (GTAW Mech./Auto.)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Traverse Length</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Traverse Speed</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Dwell Time</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Peening</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Interpass Cleaning</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Other</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>							PROCEDURE							Weld Layer(s)							Weld Pass(es)							Process							Type (Manual, Mechanized, etc.)							Position							Vertical Progression							Filler Metal (AWS Spec.)							AWS Classification							Diameter							Manufacturer/Trade Name							Shielding Gas Compos. (GTAW)							Flow Rate (GTAW)							Nozzle Size (GTAW)							Preheat Temperature							Interpass Temperature							Electrical Characteristics	—	—	—	—	—	—	Electrode Diameter (GTAW)							Current Type & Polarity							Amps							Volts							Cold or Hot Wire Feed (GTAW)							Travel Speed							Maximum Heat Input							Technique	—	—	—	—	—	—	Stringer or Weave							Multi or Single Pass (per side)							Oscillation (GTAW Mech./Auto.)							Traverse Length							Traverse Speed							Dwell Time							Peening							Interpass Cleaning							Other									
PROCEDURE																																																																																																																																																																																																																																																							
Weld Layer(s)																																																																																																																																																																																																																																																							
Weld Pass(es)																																																																																																																																																																																																																																																							
Process																																																																																																																																																																																																																																																							
Type (Manual, Mechanized, etc.)																																																																																																																																																																																																																																																							
Position																																																																																																																																																																																																																																																							
Vertical Progression																																																																																																																																																																																																																																																							
Filler Metal (AWS Spec.)																																																																																																																																																																																																																																																							
AWS Classification																																																																																																																																																																																																																																																							
Diameter																																																																																																																																																																																																																																																							
Manufacturer/Trade Name																																																																																																																																																																																																																																																							
Shielding Gas Compos. (GTAW)																																																																																																																																																																																																																																																							
Flow Rate (GTAW)																																																																																																																																																																																																																																																							
Nozzle Size (GTAW)																																																																																																																																																																																																																																																							
Preheat Temperature																																																																																																																																																																																																																																																							
Interpass Temperature																																																																																																																																																																																																																																																							
Electrical Characteristics	—	—	—	—	—	—																																																																																																																																																																																																																																																	
Electrode Diameter (GTAW)																																																																																																																																																																																																																																																							
Current Type & Polarity																																																																																																																																																																																																																																																							
Amps																																																																																																																																																																																																																																																							
Volts																																																																																																																																																																																																																																																							
Cold or Hot Wire Feed (GTAW)																																																																																																																																																																																																																																																							
Travel Speed																																																																																																																																																																																																																																																							
Maximum Heat Input																																																																																																																																																																																																																																																							
Technique	—	—	—	—	—	—																																																																																																																																																																																																																																																	
Stringer or Weave																																																																																																																																																																																																																																																							
Multi or Single Pass (per side)																																																																																																																																																																																																																																																							
Oscillation (GTAW Mech./Auto.)																																																																																																																																																																																																																																																							
Traverse Length																																																																																																																																																																																																																																																							
Traverse Speed																																																																																																																																																																																																																																																							
Dwell Time																																																																																																																																																																																																																																																							
Peening																																																																																																																																																																																																																																																							
Interpass Cleaning																																																																																																																																																																																																																																																							
Other																																																																																																																																																																																																																																																							

**Example WPS (Prequalified)
WELDING PROCEDURE SPECIFICATION (WPS)**

LECO

Company Name
C. W. Hayes
Authorized by

01/03/2015
Date

W2081

WPS No.
None (Prequalified)
Supporting PQR(s)

2
Rev. No. **No**
Date
CVN Report

BASE METALS	Specification	Type or Grade	AWS Group No.
Base Material	ASTM A36	—	II
Welded To	ASTM A36	—	II
Backing Material	ASTM A36	—	—
Other			

BASE METAL THICKNESS	As-Welded	With PWHT
CJP Groove Welds	> 3/4–2.5 in	—
CJP Groove w/CVN	—	—
PJP Groove Welds	—	—
Fillet Welds	—	—
DIAMETER	—	—


JOINT DETAILS

Groove Type	Single V Groove Butt Joint
Groove Angle	20°
Root Opening	5/8 in
Root Face	—
Backgouging	None
Method	—

POSTWELD HEAT TREATMENT

Temperature	N.A.
Time at Temperature	—
Other	—

JOINT DETAILS (Sketch)



PROCEDURE

Weld Layer(s)	All							
Weld Pass(es)	All							
Process	SAW							
Type (Semiautomatic, Mechanized, etc.)	Mechanized							
Position	F							
Filler Metal (AWS Spec.)	A5.17							
AWS Classification	EM12K							
Electrode Diameter	5/32 in							
Electrode/Flux Classification	F7A2-EM12K							
Manufacturer/Trade Name	(Flux XYZ)							
Supplemental Filler Metal	—							
Preheat Temperature	150°F min.							
Interpass Temperature	500°F max.							
Electrical Characteristics	—	—	—	—	—	—	—	—
Current Type & Polarity	DCEP							
Amps	500–600							
Volts	26–30							
Wire Feed Speed	—							
Travel Speed	20–25 ipm							
Maximum Heat Input	—							
Technique	—	—	—	—	—	—	—	—
Stringer or Weave	Stringer							
Multi or Single Pass (per side)	Multipass							
Number of Electrodes	1							
Longitudinal Spacing of Arcs	—							
Lateral Spacing of Arcs	—							
Angle of Parallel Electrodes	—							
Angle of Electrode (Mech./Auto.)	5° ± 2°							
Normal To Direction of Travel	90° ± 2°							
Oscillation (Mechanized/Automatic)	None							
Traverse Length	—							
Traverse Speed	—							
Dwell Time	—							
Peening	None							
Interpass Cleaning	Slag Removed							
Other	—							

3. Prequalification of WPSs

- 3.1 Scope
- *Prequalification of WPSs (Welding Procedure Specifications) shall be defined as exempt from the WPS qualification testing required in Clause 4.*
- *All prequalified WPSs shall be written.*
- *Welders, welding operators and tack welders that use prequalified WPSs shall be qualified in conformance with Clause 4, Part C or Clause 9, Part D for tubulars*

Table 3.1
Approved Base Metals for Prequalified WPSs (see 3.3)

G r o u p	Steel Specification Requirements				
	Steel Specification	Minimum Yield Point/Strength		Tensile Range	
		ksi	MPa	ksi	MPa
	ASTM A36 (≤3/4 in [20 mm])	36	250	58–80	400–550
	ASTM A53 Grade B	35	240	60 min.	415 min.
	ASTM A106 Grade B	35	240	60 min.	415 min.
	ASTM A131 Grades A, B, CS, D, DS, E	34	235	58–75	400–520
	ASTM A139 Grade B	35	240	60 min.	415 min.
	ASTM A381 Grade Y35	35	240	60 min.	415 min.
	ASTM A500 Grade A Grade B Grade C	33	230	45 min.	310 min.
		42	290	58 min.	400 min.
		46	315	62 min.	425 min.
	ASTM A501 <u>Grade A</u>	36	250	58 min.	400 min.
	ASTM A516 Grade 55 Grade 60	30	205	55–75	380–515
		32	220	60–80	415–550
	ASTM A524 Grade I Grade II	35	240	60–85	415–586
		30	205	55–80	380–550
	ASTM A573 Grade 65 Grade 58	35	240	65–77	450–530
		32	220	58–71	400–490
I	ASTM A709 Grade 36 (≤3/4 in [20 mm])	36	250	58–80	400–550
	ASTM A1008 SS Grade 30 Grade 33 Type 1 Grade 40 Type 1	30	205	45 min.	310 min.
		33	230	48 min.	330 min.
		40	275	52 min.	360 min.
	ASTM A1011 SS Grade 30 Grade 33 Grade 36 Type 1 Grade 40 Grade 45	30	205	49 min.	340 min.
		33	230	52 min.	360 min.
		36	250	53 min.	365 min.
		40	275	55 min.	380 min.
		45	310	60 min.	410 min.
	<u>ASTM A1018 SS</u> Grade 30 Grade 33 Grade 36 Grade 40	30	205	49 min.	340 min.
		33	230	52 min.	360 min.
		36	250	53 min.	365 min.
		40	275	55 min.	380 min.
	API 5L Grade B Grade X42	35	241	60	414
		42	290	60	414
	ABS Grades A, B, D, CS, DS Grade E ^b	34	235	58–75	400–520
		34	235	58–75	400–520

(Continued)

Table 3.1 (Continued)
Approved Base Metals for Prequalified WPSs (see 3.3)

G r o u p	Steel Specification Requirements					
	Steel Specification	Minimum Yield Point/Strength		Tensile Range		
		ksi	MPa	ksi	MPa	
	ASTM A36	(>3/4 in [20 mm])	36	250	58–80	400–550
	ASTM A131	Grades AH32, DH32, EH32	46	315	64–85	440–590
		Grades AH36, DH36, EH36	51	355	71–90	490–620
	ASTM A441		40–50	275–345	60–70	415–485
	ASTM A501	Grade B	50	345	70 min.	485 min.
	ASTM A516	Grade 65	35	240	65–85	450–585
		Grade 70	38	260	70–90	485–620
	ASTM A529	Grade 50	50	345	70–100	485–690
		Grade 55	55	380	70–100	485–690
	ASTM A537	Class 1	45–50	310–345	65–90	450–620
	ASTM A572	Grade 42	42	290	60 min.	415 min.
		Grade 50	50	345	65 min.	450 min.
		Grade 55	55	380	70 min.	485 min.
	ASTM A588 ^b	(4 in [100 mm] and under)	50	345	70 min.	485 min.
	ASTM A595	Grade A	55	380	65 min.	450 min.
		Grades B and C	60	410	70 min.	480 min.
	ASTM A606 ^b		45–50	310–340	65 min.	450 min.
	ASTM A618	Grades Ib, II, III	46–50	315–345	65 min.	450 min.
II	ASTM A633	Grade A	42	290	63–83	430–570
		Grades C, D (2-1/2 in [65 mm] and under)	50	345	70–90	485–620
	ASTM A709	Grade 36 (>3/4 in [20 mm])	36	250	58–80	400–550
		Grade 50	50	345	65 min.	450 min.
		Grade 50W ^b	50	345	70 min.	485 min.
		Grade 50S	50–65	345–450	65 min.	450 min.
		Grade HPS 50W ^b	50	345	70 min.	485 min.
	ASTM A710	Grade A, Class 2 (>2 in [50 mm])	50–55	345–380	60–65	415–450
	ASTM A808	(2-1/2 in [65 mm] and under)	42	290	60 min.	415 min.
	ASTM A913	Grade 50	50	345	65 min.	450 min.
	ASTM A992		50–65	345–450	65 min.	450 min.
	ASTM A1008 HSLAS	Grade 45 Class 1	45	310	60 min.	410 min.
		Grade 45 Class 2	45	310	55 min.	380 min.
		Grade 50 Class 1	50	340	65 min.	450 min.
		Grade 50 Class 2	50	340	60 min.	410 min.
		Grade 55 Class 1	55	380	70 min.	480 min.
		Grade 55 Class 2	55	380	65 min.	450 min.
	ASTM A1008 HSLAS-F	Grade 50	50	340	60 min.	410 min.

(Continued)

Table 3.1 (Continued)
Approved Base Metals for Prequalified WPSs (see 3.3)

G r o u p	Steel Specification Requirements				
	Steel Specification	Minimum Yield Point/Strength		Tensile Range	
		kst	MPa	kst	MPa
I	ASTM A1011 HSLAS	Grade 45 Class 1	45	310	60 min.
		Grade 45 Class 2	45	310	55 min. 380 min.
		Grade 50 Class 1	50	340	65 min. 450 min.
		Grade 50 Class 2	50	340	60 min. 410 min.
		Grade 55 Class 1	55	380	70 min. 480 min.
		Grade 55 Class 2	55	380	65 min. 450 min.
II (Cont'd)	ASTM A1011 HSLAS-F	Grade 50	50	340	60 min. 410 min.
	ASTM A1011 SS	Grade 50	50	340	65 min. 450 min.
		Grade 55	55	380	70 min. 480 min.
	ASTM A1018 HSLAS	Grade 45 Class 1	45	310	60 min. 410 min.
		Grade 45 Class 2	45	310	55 min. 380 min.
		Grade 50 Class 1	50	340	65 min. 450 min.
		Grade 50 Class 2	50	340	60 min. 410 min.
		Grade 55 Class 1	55	380	70 min. 480 min.
		Grade 55 Class 2	55	380	65 min. 450 min.
III	ASTM A1018 HSLAS-F	Grade 50	50	340	60 min. 410 min.
	ASTM A1085		50–70	345–485	65 min. 450 min.
		API 2H	Grade 42	42	289
			Grade 50	50	345
	API 2MT1	Grade 50	50	345	70–90 483–620
	API 2W	Grade 42	42–67	290–462	62 min. 427 min.
		Grade 50	50–75	345–517	65 min. 448 min.
		Grade 50T	50–80	345–552	70 min. 483 min.
IV	API 2Y	Grade 42	42–67	290–462	62 min. 427 min.
		Grade 50	50–75	345–517	65 min. 448 min.
		Grade 50T	50–80	345–552	70 min. 483 min.
V	API 5L	Grade X52	52	359	66 min. 455 min.
		Grades AH32, DH32, EH32	46	315	64–85 440–590
		Grades AH36, DH36, EH36 ^b	51	355	71–90 490–620

(Continued)

Table 3.1 (Continued)
Approved Base Metals for Prequalified WPSs (see 3.3)

G r o u p	Steel Specification Requirements				
	Steel Specification	ksi	MPa	ksi	MPa
III	API 2W	Grade 60	60–90	414–621	75 min.
	API 2Y	Grade 60	60–90	414–621	75 min.
	ASTM A537	Class 2 ^b	46–60	315–415	70–100
	ASTM A572	Grade 60	60	415	75 min.
		Grade 65	65	450	80 min.
	ASTM A633	Grade E ^b	55–60	380–415	75–100
	ASTM A710	Grade A, Class 2 (≤2 in [50 mm])	60–65	415–450	72 min.
	ASTM A710	Grade A, Class 3 (>2 in [50 mm])	60–65	415–450	70–75
	ASTM A913 ^a	Grade 60	60	415	75 min.
		Grade 65	65	450	80 min.
IV	ASTM A1018 HSLAS	Grade 60 Class 2	60	410	70 min.
		Grade 70 Class 2	70	480	80 min.
	ASTM A1018 HSLAS-F	Grade 60 Class 2	60	410	70 min.
		Grade 70 Class 2	70	480	80 min.
	ASTM A709	Grade HPS 70W	70	485	85–110
IV	ASTM A852		70	485	90–110
	ASTM A913 ^a	Grade 70	70	485	90 min.
620–760					

^a The heat input limitations of 5.7 shall not apply to ASTM A913 Grade 60, 65, or 70.

^b Special welding materials and WPS (e.g., E80XX-X low-alloy electrodes) may be required to match the notch toughness of base metal (for applications involving impact loading or low temperature), or for atmospheric corrosion and weathering characteristics (see 3.7.3).

Notes:

1. In joints involving base metals of different groups, either of the following filler metals may be used: (1) that which matches the higher strength base metal, or (2) that which matches the lower strength base metal and produces a low-hydrogen deposit. Preheating shall be in conformance with the requirements applicable to the higher strength group.
2. Match API standard 2B (fabricated tubes) according to steel used.
3. When welds are to be stress-relieved, the deposited weld metal shall not exceed 0.05% vanadium.
4. See Tables 2.3 and 9.2 for allowable stress requirements for matching filler metal.
5. Filler metal properties have been moved to nonmandatory Annex T.
6. AWS A5M (SI Units) electrodes of the same classification may be used in lieu of the AWS A5 (U.S. Customary Units) electrode classification.
7. Any of the electrode classifications for a particular Group in Table 3.2 may be used to weld any of the base metals in that Group in Table 3.1.

Table 3.2
Filler Metals for Matching Strength to Table 3.1,
Groups I, II, III, and IV Metals—SMAW and SAW (see 3.3)

Base Metal Group	AWS Electrode Specification	SMAW		SAW	
		A5.1, Carbon Steel	A5.5 ^a , Low-Alloy Steel	A5.17, Carbon Steel	A5.23 ^c , Low-Alloy Steel
I	AWS Electrode Classification	E60XX	E70XX-X	F6XX-EXXX	F7XX-EXXX-XX
		E70XX		F6XX-ECXXX	F7XX-ECXXX-XX
				F7XX-EXXX	
				F7XX-ECXXX	
II	AWS Electrode Classification	E7015	E7015-X	F7XX-EXXX	F7XX-EXXX-XX
		E7016	E7016-X	F7XX-ECXXX	F7XX-ECXXX-XX
		E7018	E7018-X		
		E7028			
III	AWS Electrode Classification	N/A	E8015-X	N/A	F8XX-EXXX-XX
			E8016-X		F8XX-ECXXX-XX
			E8018-X		
IV	AWS Electrode Classification	N/A	E9015-X	N/A	F9XX-EXXX-XX
			E9016-X		F9XX-ECXXX-XX
			E9018-X		
			E9018M		

(Continued)

- **3.5 Minimum Preheat and Interpass Temperature Requirements**
- *Table 3.3 shall be used to determine the minimum preheat and interpass temperatures for steels listed in the code.*
- **3.5.1 Base Metal/Thickness Combination.** *The minimum preheat or interpass temperature applied to a joint composed of base metals with different minimum preheats from Table 3.3 (based on Category and thickness) shall be the highest of these minimum preheats*

Table 3.3
Prequalified Minimum Preheat and Interpass Temperature (see 3.5)

Category	Steel Specification	Welding Process	Thickness of Thickest Part at Point of Welding		Minimum Preheat and Interpass Temperature	
			in	mm	°F	°C
A	ASTM A36	SMAW with other than low-hydrogen electrodes	1/8 to 3/4 incl.	3 to 20 incl.	32 ^a	0 ^a
	ASTM A53					
	Grade B					
	ASTM A106					
	Grade B					
	ASTM A131					
	Grades A, B, CS, D, DS, E					
	ASTM A139					
	Grade B					
	ASTM A381					
	Grade Y35					
	ASTM A500					
	Grade A					
	Grade B					
	Grade C					
	ASTM A501					
	<u>Grade A</u>					
B	ASTM A516					
	ASTM A524					
	Grades I & II					
	ASTM A573					
	Grade 65					
	ASTM A709					
	Grade 36					
	ASTM A1008 SS					
	Grade 30					
	Grade 33 Type 1					
	Grade 40 Type 1					
	ASTM A1011 SS					
	Grade 30					
	Grade 33					
	Grade 36 Type 1					
	Grade 40					
	Grade 45					
	Grade 50					
	Grade 55					
C	<u>ASTM A1018 SS</u>	SMAW with low-hydrogen electrodes, SAW, GMAW, FCAW	Over 3/4 thru 1-1/2 incl.	Over 20 thru 38 incl.	150	65
	Grade 30					
	Grade 33					
	Grade 36					
	Grade 40					
	API 5L					
	Grade B					
	Grade X42					
	ABS					
	Grades A, B, D, CS, DS					
	Grade E					

(Continued)

Table 3.3 (Continued)
Prequalified Minimum Preheat and Interpass Temperature (see 3.5)

Category	Steel Specification	Welding Process	Thickness of Thickest Part at Point of Welding		Minimum Preheat and Interpass Temperature	
			in	mm	°F	°C
B (Cont'd)	ASTM A537	SMAW with low-hydrogen electrodes, SAW, GMAW, FCAW	1/8 to 3/4 incl.	3 to 20 incl.	32 ^a	0 ^a
	ASTM A572					
	ASTM A573					
	ASTM A588					
	ASTM A595					
	ASTM A606					
	ASTM A618					
	ASTM A633					
	ASTM A709					
	ASTM A710					
	ASTM A808					
	ASTM A913 ^b					
	ASTM A992					
	ASTM A1008 HSLAS					
	ASTM A1008 HSLAS-F					
	ASTM A1011 HSLAS					
	ASTM A1011 HSLAS-F					
	ASTM A1018 HSLAS					
	ASTM A1018 HSLAS-F					
	ASTM A1018 SS					
	ASTM 1085					
	API 5L					
	API Spec. 2H					
	API 2MT1					
	API 2W					
	API 2Y					
	ABS					

(Continued)

Table 3.3 (Continued)
Prequalified Minimum Preheat and Interpass Temperature (see 3.5)

Category	Steel Specification	Welding Process	Thickness of Thickest Part at Point of Welding		Minimum Preheat and Interpass Temperature	
			in	mm	°F	°C
C	ASTM A572	Grades 60, 65	SMAW with low-hydrogen electrodes, SAW, GMAW, FCAW	1/8 to 3/4 incl.	3 to 20 incl.	50 10
	ASTM A633	Grade E				
	ASTM A913 ^b	Grades 60, 65, 70		Over 3/4 thru 1-1/2 incl.	Over 20 thru 38 incl.	150 65
	ASTM A710	Grade A, Class 2 (≤2 in [50 mm])				
	ASTM A710	Grade A, Class 3 (>2 in [50 mm])		Over 1-1/2 thru 2-1/2 incl.	Over 38 thru 65 incl.	225 110
	ASTM A709 ^c	Grade HPS 70W				
	ASTM A852 ^c			Over 2-1/2	Over 65	300 150
	ASTM A1018	Grade 60 Class 2 HSLAS				
	ASTM A1018	Grade 60 Class 2 HSLAS-F		All thicknesses ≥ 1/8 in [3 mm]	32 ^a 0 ^a	
	API 2W	Grade 60				
	API 2Y	Grade 60				
	API 5L	Grade X52				
D	ASTM A710	Grade A (All classes)	SMAW, SAW, GMAW, and FCAW with electrodes or electrode-flux combinations capable of depositing weld metal with a maximum diffusible hydrogen content of 8 ml/100 g (H8), when tested according to AWS A4.3.	All thicknesses ≥ 1/8 in [3 mm]	32 ^a 0 ^a	
	ASTM A913 ^b	Grades 50, 60, 65				

^a When the base metal temperature is below 32°F [0°C], the base metal shall be preheated to a minimum of 70°F [20°C] and the minimum interpass temperature shall be maintained during welding.

^b The heat input limitations of 5.7 shall not apply to ASTM A913.

^c For ASTM A709 Grade HPS 70W and ASTM A852, the maximum preheat and interpass temperatures shall not exceed 400°F [200°C] for thicknesses up to 1-1/2 in [40 mm], inclusive, and 450°F [230°C] for greater thicknesses.

Notes:

1. For modification of preheat requirements for SAW with parallel or multiple electrodes, see 3.5.2.
2. See 5.11.2 and 5.6 for ambient and base metal temperature requirements.

- 3.6 Limitation of WPS Variables
- *All prequalified WPSs to be used shall be prepared by the manufacturer, fabricator, or Contractor as written prequalified WPSs. The written WPS may follow any convenient format (see Annex M for examples).*
- *The welding parameters set forth in Table 3.6 shall be specified on the written WPS, and for variables with limits, within the range shown.*
- *Changes to the essential variables beyond those permitted by Table 3.7 shall require a new or revised prequalified WPS, or shall require that the WPS be qualified by test in accordance with Clause 4.*

Table 3.6
Prequalified WPS Requirements^f (see 3.7)

Variable	Position	Weld Type	SMAW	SAW ^d			GMAW/ FCAW ^g	
				Single	Parallel	Multiple		
Maximum Electrode Diameter	Flat	Fillet ^a	5/16 in [8.0 mm]	1/4 in [6.4 mm]			1/8 in [3.2 mm]	
		Groove ^a	1/4 in [6.4 mm]					
		Root pass	3/16 in [4.8 mm]				1/8 in [3.2 mm]	
	Horizontal	Fillet	1/4 in [6.4 mm]	1/4 in [6.4 mm]				
		Groove	3/16 in [4.8 mm]	Requires WPS Qualification Test			3/32 in [2.4 mm]	
	Vertical	All	3/16 in [4.8 mm] ^b					
	Overhead	All	3/16 in [4.8 mm] ^b				5/64 in [2.0 mm]	
Maximum Current	All	Fillet	Within the range of recommended operation by the filler metal manufacturer	1000 A	1200A	Unlimited	Within the range of recommended operation by the filler metal manufacturer	
	All	Groove weld root pass with opening		600A	700A			
		Groove weld root pass without opening			900A			
		Groove weld fill passes			1200A			
		Groove weld cap pass			Unlimited			
Maximum Root Pass Thickness ^d	Flat	All	3/8 in [10 mm]	Unlimited			3/8 in [10 mm]	
	Horizontal		5/16 in [8 mm]				5/16 in [8 mm]	
	Vertical		1/2 in [12 mm]				1/2 in [12 mm]	
	Overhead		5/16 in [8 mm]				5/16 in [8 mm]	
Maximum Fill Pass Thickness	All	All	3/16 in [5 mm]	1/4 in [6 mm]	Unlimited		1/4 in [6 mm]	
Maximum Single Pass Fillet Weld Size ^c	Flat	Fillet	3/8 in [10 mm]	Unlimited			1/2 in [12 mm]	
	Horizontal		5/16 in [8 mm]	5/16 in [8 mm]	5/16 in [8 mm]	1/2 in [12 mm]	3/8 in [10 mm]	
	Vertical		1/2 in [12 mm]				1/2 in [12 mm]	
	Overhead		5/16 in [8 mm]				5/16 in [8 mm]	
Maximum Single Pass Layer Width	All (for GMAW/ FCAW) F & H (for SAW)	Root opening > 1/2 in [12 mm], or	Any layer of width w	Split layers	Laterally displaced electrodes or split layer	Split layers	Split layers	
		Any layer of width w		Split layers if w > 5/8 in [16 mm]	Split layers with tandem electrodes if w > 5/8 in [16 mm]	If w > 1 in [25 mm], split layers	(Note e)	

^a Except root passes.

^b 5/32 in [4.0 mm] for EXX14 and low-hydrogen electrodes.

^c See 3.7.3 for requirements for welding unpainted and exposed ASTM A588.

^d See 3.7.2 for width-to-depth limitations.

^e In the F, H, or OH positions for nontubulars, split layers when the layer width w > 5/8 in [16 mm]. In the vertical position for nontubulars or the flat, horizontal, vertical, and overhead positions for tubulars, split layers when the width w > 1 in [25 mm].

^f Shaded area indicates nonapplicability.

^g GMAW-S shall not be prequalified.

Table 3.7
Prequalified WPS Variables (see 3.6 and 3.7)

Prequalified WPS Variable	Process			
	SMAW	SAW	GMAW	FCAW
General				
1) A change in welding process(es) ^a	X	X	X	X
2) A change in welding position(s)	X	X	X	X
Base Metal				
3) A change in base metal group number(s) (see Table 3.1)	X	X	X	X
4) A change in the base metal preheat category (see Table 3.3)	X	X	X	X
Filler Metal				
5) A change in electrode classification(s)	X	X	X	X
6) A change in electrode/flux classification(s)		X		
7) A change in nominal electrode diameter(s)	X	X	X	X
8) A change in the number of electrodes		X		
Process Parameters				
9) A change in amperage		> 10% increase or decrease	> 10% increase or decrease	> 10% increase or decrease
10) A change in type of current (ac or dc) or polarity	X	X	X	X
11) A change in the mode of transfer			X	
12) A change in voltage		> 15% increase or decrease	> 15% increase or decrease	> 15% increase or decrease
13) A change in wire feed speed (if not amperage controlled)		> 10% increase or decrease	> 10% increase or decrease	> 10% increase or decrease
14) A change in travel speed		> 25% increase or decrease	> 25% increase or decrease	> 25% increase or decrease
Shielding Gas				
15) A change in the nominal composition of shielding gas			X	X (for FCAW-G only)
16) A decrease in shielding gas flow rate			> 25%	> 25% (for FCAW-G only)
17) An increase in the gas flow rate			> 50%	> 50% (for FCAW-G only)

(Continued)

Table 3.7 (Continued)
Prequalified WPS Variables (see 3.6 and 3.7)

Prequalified WPS Variable	Process			
	SMAW	SAW	GMAW	FCAW
SAW Parameters				
18) A change in the longitudinal spacing of arcs		> 10% or 1/8 in [3 mm], whichever is greater		
19) A change in the lateral spacing of arcs		> 10% or 1/8 in [3 mm], whichever is greater		
20) A change in the angular orientation of parallel electrodes		Increase or decrease > 10°		
21) For mechanized or automatic SAW, a change in the angle <u>parallel to the direction of travel</u> of the electrode		Increase or decrease > 10°		
22) For mechanized or automatic SAW, a change in the angle of electrode normal to the direction of travel		Increase or decrease > 15°		
Weld Details				
23) A change in the weld configuration (e.g., a fillet to a CJP groove weld, etc.)	X	X	X	X
24) A change in groove weld detail(s) as shown in Figures 3.2, 3.3, and 3.6	X	X	X	X
Thermal				
25) A change in PWHT (the addition of, deletion of) ^a	X	X	X	X

^aA separate WPS shall be required when this variable is changed.

Note: An "X" indicates applicability for the process; a shaded block indicates nonapplicability.

- **3.7 General WPS Requirements**
- *All the requirements of Table 3.6 shall be met for prequalified WPSs.*
- **3.7.1 Vertical-Up Welding Requirements.** *The progression for all passes in vertical position welding shall be upward, with the following exceptions:*
 - *(1) Undercut may be repaired vertically downwards when preheat is in conformance with Table 3.3, but not lower than 70°F [20°C].*
 - *(2) When tubular products are welded, the progression of vertical welding may be upwards or downwards, but only in the direction(s) for which the welder is qualified.*
- **3.7.2 Width/Depth Pass Limitation.** *Neither the depth nor the maximum width in the cross section of weld metal deposited in each weld pass shall exceed the width at the surface of the weld pass (see Figure 3.1).*





Figure 3.1—Weld Bead in which Depth and Width Exceed the Width of the Weld Face (see 3.7.2)




Figure C-3.2—Examples of Centerline Cracking (see C-3.7.2)

• 3.9 Fillet Weld Requirements

- See Table 5.7 for minimum fillet weld sizes and Figure 3.5 for prequalified fillet weld joint details.
- 3.9.1 Details (Nontubular). See Figures 2.1 and 2.4 for the limitations for prequalified fillet welds.
- 3.9.2 Skewed T-Joints. *Skewed T-joints shall be in conformance with Figure 3.4.*
- 3.9.2.1 Dihedral Angle Limitations. *The obtuse side of skewed T-joints with dihedral angles greater than 100° shall be prepared as shown in Figure 3.4, Detail C, to allow placement of a weld of the required size. The amount of machining or grinding, etc., of Figure 3.4, Detail C, should not be more than that required to achieve the required weld size (W).*
- 3.9.2.2 Minimum Weld Size for Skewed T-Joints. *For skewed T-joints, the minimum weld size for Details A, B, and C in Figure 3.4 shall be in conformance with Table 5.7.*

Table 5.7
Minimum Fillet Weld Sizes (see 5.13)


Base Metal Thickness (T) ^a		Minimum Size of Fillet Weld ^b	
in	mm	in	mm
T ≤ 1/4	T ≤ 6	1/8 ^c	3 ^c
1/4 < T ≤ 1/2	6 < T ≤ 12	3/16	5
1/2 < T ≤ 3/4	12 < T ≤ 20	1/4	6
3/4 < T	20 < T	5/16	8

^a For nonlow-hydrogen processes without preheat calculated in conformance with 4.8.4, T equals thickness of the thicker part joined; single-pass welds shall be used.

For nonlow-hydrogen processes using procedures established to prevent cracking in conformance with 4.8.4 and for low-hydrogen processes, T equals thickness of the thinner part joined; single-pass requirement shall not apply.

^b Except that the weld size need not exceed the thickness of the thinner part joined.


^c Minimum size for cyclically loaded structures shall be 3/16 in [5 mm].



BASE METAL LESS THAN
1/4 in [6 mm] THICK

(A)


MAXIMUM DETAILED SIZE OF FILLET WELD ALONG EDGES



BASE METAL 1/4 in [6 mm]
OR MORE IN THICKNESS

(B)

**Figure 2.1—Maximum Fillet Weld Size
Along Edges in Lap Joints (see 2.4.2.9)**



(NOT LESS THAN 1 in [25 mm])

Note: t = thicker member, t_1 = thinner member.

**Figure 2.4—Transversely Loaded
Fillet Welds (see 2.9.9.1 and 2.9.1.2)**

Notes for Figure 3.5

^a Fillet weld size ("S"). See 2.4.2.8 and Clause 5.14 for minimum fillet weld sizes. See Table 3.7 for maximum single pass size.

^b See 5.22.1 for additional fillet weld assembly requirements or exceptions.

^c See 2.4.2.9 for maximum weld size in lap joints.


^d Perpendicularity of the members shall be within $\pm 10^\circ$.

Fillet weld (12)

T-joint (T)

Corner joint (C)

Lap joint (L)




ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness T ₁ or T ₂	Joint Design/Geometry			Allowed Welding Positions	Notes		
			Root Opening	Tolerances					
				As Detailed	As Fit-Up				
SMAW	TC-F12	<3	R = 0	+1/16, -0	3/16 max.	All	a, b, d		
	TC-F12a	≥3			5/16 max.		a, b, d		
	L-F12	<3			3/16 max.		a, b, c		
	L-F12a	≥3			5/16 max.		a, b, c		
FMAW FCAW	TC-F12-GF	<3	R = 0	+1/16, -0	3/16 max.	All	a, b, d		
	TC-F12a-GF	≥3			5/16 max.		a, b, d		
	L-F12-GF	<3			3/16 max.		a, b, c		
	L-F12a-GF	≥3			5/16 max.		a, b, c		
SAW	TC-F12-S	<3	R = 0	+1/16, -0	3/16 max.	F, H	a, b, d		
	TC-F12a-S	≥3			5/16 max.		a, b, d		
	L-F12-S	<3			3/16 max.		a, b, c		
	L-F12a-S	≥3			5/16 max.		a, b, c		

**Figure 3.5—Prequalified Fillet Weld Joint Details
(Dimensions in Inches) (see 3.9)**


Fillet weld (12)
T-joint (T)
Corner joint (C)
Lap joint (L)




ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness	Joint Design/Geometry			Allowed Welding Positions	Notes
			T ₁ or T ₂	Root Opening	Tolerances		
					As Detailed		
SMAW	TC-F12	<75	R = 0	+2, -0	5 max.	All	a, b, d
	TC-F12a	≥75			8 max.		a, b, d
	L-F12	<75			5 max.		a, b, c
	L-F12a	≥75			8 max.		a, b, c
FMAW FCAW	TC-F12-GF	<75	R = 0	+2, -0	5 max.	All	a, b, d
	TC-F12a-GF	≥75			8 max.		a, b, d
	L-F12-GF	<75			5 max.		a, b, c
	L-F12a-GF	≥75			8 max.		a, b, c
SAW	TC-F12-S	<75	R = 0	+2, -0	5 max.	F, H	a, b, d
	TC-F12a-S	≥75			8 max.		a, b, d
	L-F12-S	<75			5 max.		a, b, c
	L-F12a-S	≥75			8 max.		a, b, c



Figure 3.5 (Continued)—Prequalified Fillet Weld Joint Details
(Dimensions in Millimeters) (see 3.9)



(A)



(B)



^a Detail (D). Apply Z loss dimension of Table 2.2 to determine effective throat.


^b Detail (D) shall not be prequalified for under 30°. For welder qualifications, see Table 4.10.

Notes:

1. $(E_n), (E'_n)$ = Effective throats dependent on magnitude of root opening (R_n) (see 5.21.1). (n) represents 1 through 5.
2. t = thickness of thinner part
3. Not prequalified for GMAW-S or GTAW.

Figure 3.4—Prequalified Skewed T-Joint Details (Nontubular) (see 3.9.2)

- *3.11 Common Requirements of PJP and CJP Groove Welds*
- 3.11.1 FCAW/GMAW in SMAW Joints. *Groove preparations detailed for prequalified SMAW joints may be used for prequalified GMAW or FCAW.*
- 3.11.2 Corner Joint Preparation. *For corner joints, the outside groove preparation may be in either or both members, provided the basic groove configuration is not changed and adequate edge distance is maintained to support the welding operations without excessive melting.*



β INVOLVES PREPARATION IN BOTH PLATES IN THE CORNER JOINT. USED WHEN, FOR A MINIMUM "a" THICKNESS, THE VERTICAL PLATE CANNOT ACCOMMODATE α GROOVE ANGLE.




Figure C-3.3—Details of Alternative Groove Preparations for Prequalified Corner Joints
(see C-3.11.2)

- 3.11.3 Root Openings. *Joint root openings may vary as noted in 3.12.3 and 3.13.1. However, for automatic or mechanized welding using FCAW, GMAW, and SAW processes, the maximum root opening variation (minimum to maximum opening as fit-up) may not exceed 1/8 in [3 mm]. Variations greater than 1/8 in [3 mm] shall be locally corrected prior to automatic or mechanized welding.*

- **3.12 PJP Requirements**

- *PJP groove welds shall be made using the joint details described in Figure 3.2. The joint dimensional limitations described in 3.12.3 shall apply.*
- 3.12.1 Definition. *Except as provided in 9.11.2 and Figure 3.3 (B-L1-S), groove welds without steel backing, welded from one side, and groove welds welded from both sides, but without back gouging, are considered PJP groove welds.*

- 3.12.2 Weld Size. *The weld size (E) of a prequalified PJP groove shall be as shown in Figure 3.2 for the particular welding process, joint designation, groove angle, and welding position proposed for use in welding fabrication.*
- 3.12.2.1 Prequalified Weld Sizes
- (1) *The minimum weld size of PJP single- or double- V, bevel-, J-, and U-groove welds, types 2 through 9, shall be as shown in Table 3.5. The base metal thickness shall be sufficient to incorporate the requirements of the joint details selected, conforming to the variances outlined in 3.12.3 and the requirements of Table 3.5.*
- (2) *The maximum base metal thickness shall not be limited.*
- (3) *The PJP square groove weld B-P1 and flare-bevel groove welds BTC-P10 and B-P11 minimum weld sizes shall be calculated from Figure 3.2.*
- (4) *Shop or working drawings shall specify the design grooves depths “S” applicable for the weld size “(E)” required per 3.12.2. (Note that this requirement shall not apply to the B-P1, BTC-P10, and B-P11 details.)*

Table 3.5
Minimum Prequalified PJP Weld Size (E)
(see 3.12.2.1)

Base Metal Thickness (T) ^a	Minimum Weld Size ^b	
	in [mm]	in mm
1/8 [3] to 3/16 [5] incl.	1/16	2
Over 3/16 [5] to 1/4 [6] incl.	1/8	3
Over 1/4 [6] to 1/2 [12] incl.	3/16	5
Over 1/2 [12] to 3/4 [20] incl.	1/4	6
Over 3/4 [20] to 1-1/2 [38] incl.	5/16	8
Over 1-1/2 [38] to 2-1/4 [57] incl.	3/8	10
Over 2-1/4 [57] to 6 [150] incl.	1/2	12
Over 6 [150]	5/8	16

^a For nonlow-hydrogen processes without preheat calculated in conformance with 4.8.4, T equals the thickness of the thicker part joined; single pass welds shall be used. For low-hydrogen processes and nonlow-hydrogen processes established to prevent cracking in conformance with 4.8.4, T equals thickness of the thinner part; single pass requirement does not apply.

^b Except that the weld size need not exceed the thickness of the thinner part joined.

- 3.12.3 Joint Dimensions
- (1) *Dimensions of groove welds specified in 3.12 may vary on design or detail drawings within the limits of tolerances shown in the “As Detailed” column in Figure 3.2.*
- (2) *Fit-up tolerances of Figure 3.2 may be applied to the dimensions shown on the detail drawing. However, the use of fit-up tolerances does not exempt the user from meeting the minimum weld size requirements of 3.12.2.1.*
- (3) *J- and U-grooves may be prepared before or after assembly.*

• **3.13 CJP Groove Weld Requirements**

- *CJP groove welds which may be used without performing the WPS qualification test described in Clause 4 shall be as detailed in Figure 3.3 and are subject to the limitations described in 3.13.1.*
- **3.13.1 Joint Dimensions.** *Dimensions of groove welds specified in 3.13 may vary on design or detail drawings within the limits or tolerances shown in the “As Detailed” column in Figure 3.3. Fit-up tolerance of Figure 3.3 may be applied to the dimension shown on the detail drawing.*
- **3.13.2 Backing.** *Prequalified CJP groove welds made from one side only, except as allowed for tubular structures, shall have steel backing.*
- **3.13.2.1** *Prequalified CJP groove welds detailed without steel backing or spacers may use backing other than steel as listed in 5.9.3 when the following conditions are met:*
 - *(1) The backing is removed after welding, and,*
 - *(2) The back side of the weld is backgouged to sound metal and back welded.*

- *Welding procedures for joints welded with backing other than steel in which the weld is to be left in the as-welded condition without backgouging and welding from the other side are not prequalified.*
- **3.13.3 Double-Sided Groove Preparation.** *J- and U-grooves and the other side of partially welded double-V and double-bevel grooves may be prepared before or after assembly. After backgouging, the other side of partially welded double-V or double-bevel joints should resemble a prequalified U- or J-joint configuration at the joint root.*

Legend for Figures 3.2 and 3.3

Symbols for joint types

- B — butt joint
 - C — corner joint
 - T — T-joint
 - BC — butt or corner joint
 - TC — T- or corner joint
 - BTC — butt, T-, or corner joint
-

Symbols for base metal thickness and penetration

- P — PJP
 - L — limited thickness-CJP
 - U — unlimited thickness-CJP
-

Symbol for weld types

- 1 — square-groove
 - 2 — single-V-groove
 - 3 — double-V-groove
 - 4 — single-bevel-groove
 - 5 — double-bevel-groove
 - 6 — single-U-groove
 - 7 — double-U-groove
 - 8 — single-J-groove
 - 9 — double-J-groove
 - 10 — flare-bevel-groove
 - 11 — flare-V-groove
-

Symbols for welding processes if not SMAW

- S — SAW
 - G — GMAW
 - F — FCAW
-

Welding processes

- SMAW — shielded metal arc welding
 - GMAW — gas metal arc welding
 - FCAW — flux cored metal arc welding
 - SAW — submerged arc welding
-

Welding positions

- F — flat
 - H — horizontal
 - V — vertical
 - OH — overhead
-

Dimensions

- R = Root Opening
 - α, β = Groove Angles
 - f = Root Face
 - r = J- or U-groove Radius
 - S, S_1 , S_2 = PJP Groove Weld Depth of Groove
 - E, E_1 , E_2 = PJP Groove Weld Sizes corresponding to S, S_1 , S_2 , respectively
-


Joint Designation

The lower case letters, e.g., a, b, c, etc., are used to differentiate between joints that would otherwise have the same joint designation.

- Notes for Figures 3.2 and 3.3
- ^a Not prequalified for GMAW-S nor GTAW.
- ^b Joint shall be welded from one side only.
- ^c Cyclic load application places restrictions on the use of this detail for butt joints in the flat position (see 2.18.2).
- ^d Backgouge root to sound metal before welding second side.
- ^e SMAW detailed joints may be used for prequalified GMAW (except GMAW-S) and FCAW.
- ^f Minimum weld size (E) as shown in Table 3.5. S as specified on drawings.
- ^g If fillet welds are used in statically loaded structures to reinforce groove welds in corner and T-joints, these shall be equal to T1/4, but need not exceed 3/8 in [10 mm]. Groove welds in corner and T-joints of cyclically loaded structures shall be reinforced with fillet welds equal to T1/4, but need not exceed 3/8 in [10 mm].
- ^h Double-groove welds may have grooves of unequal depth, but the depth of the shallower groove shall be no less than one-fourth of the thickness of the thinner part joined.
- ⁱ Double-groove welds may have grooves of unequal depth, provided these conform to the limitations of Note f. Also the weld size (E) applies individually to each groove.
- ^j The orientation of the two members in the joints may vary from 135° to 180° for butt joints, or 45° to 135° for corner joints, or 45° to 90° for T-joints.
- ^k For corner joints, the outside groove preparation may be in either or both members, provided the basic groove configuration is not changed and adequate edge distance is maintained to support the welding operations without excessive edge melting.
- ^l Weld size (E) shall be based on joints welded flush.
- ^m For flare-V-groove welds and flare-bevel-groove welds to rectangular tubular sections, r shall be as two times the wall thickness.
- ⁿ For flare-V-groove welds to surfaces with different radii r, the smaller r shall be used.
- ^o For corner and T-joints the member orientation may vary from 90° to less than or equal to 170° provided the groove angle and root opening are maintained, and the angle between the groove faces and the steel backing is at least 90°. See Figure 3.6

Square-groove weld (1)


Butt joint (B)



Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Weld Size (E)	Notes		
		T_1	T_2	Root Opening	Tolerances					
					As Detailed (see 3.12.3)	As Fit-Up (see 3.12.3)				
SMAW	B-P1a	3	—	$R = 0 \text{ to } 2$	+2, -0	±2	All	$T_1 - 1$		
	B-P1c	6 max.	—	$R = \frac{T_1}{2} \text{ min.}$	+2, -0	±2	All	$\frac{T_1}{2}$		
GMAW FCAW	B-P1a-GF	3	—	$R = 0 \text{ to } 2$	+2, -0	±2	All	$T_1 - 1$		
	B-P1c-GF	6 max.	—	$R = \frac{T_1}{2} \text{ min.}$	+2, -0	±2	All	$\frac{T_1}{2}$		

Square-groove weld (1)

Butt joint (B)



$E_1 + E_2$ MUST NOT EXCEED $\frac{3T_1}{4}$

ALL DIMENSIONS IN mm


Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Total Weld Size ($E_1 + E_2$)	Notes		
		T_1	T_2	Root Opening	Tolerances					
					As Detailed (see 3.12.3)	As Fit-Up (see 3.12.3)				
SMAW	B-P1b	6 max.	—	$R = \frac{T_1}{2}$	+2, -0	±2	All	$\frac{3T_1}{4}$		
GMAW FCAW	B-P1b-GF	6 max.	—	$R = \frac{T_1}{2}$	+2, -0	±2	All	$\frac{3T_1}{4}$		

Figure 3.2 (Continued)—Prequalified PJP Groove Welded Joint Details
(see 3.12) (Dimensions in Millimeters)

Single-V-groove weld (2)

Butt joint (B)


Corner joint (C)



ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Weld Size (E)	Notes	
				Root Opening	Tolerances					
		T ₁	T ₂		Root Face	Groove Angle				
SMAW	BC-P2	6 min.	U	R = 0 f = 1 min. α = 60°	+2, -0 +U, -0 +10°, -0°	+3, -2 ±2 +10°, -5°	All	S	b, e, f, j	
GMAW FCAW	BC-P2-GF	6 min.	U	R = 0 f = 3 min. α = 60°	+2, -0 +U, -0 +10°, -0°	+3, -2 ±2 +10°, -5°	All	S	a, b, f, j	
SAW	BC-P2-S	11 min.	U	R = 0 f = 6 min. α = 60°	±0 +U, -0 +10°, -0°	+2, -0 ±2 +10°, -5°	F	S	b, f, j	

Double-V-groove weld (3)
Butt joint (B)



ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Total Weld Size (E ₁ + E ₂)	Notes	
		T ₁	T ₂	Root Opening	Tolerances				
				Root Face	Groove Angle	As Detailed (see 3.12.3)	As Fit-Up (see 3.12.3)		
SMAW	B-P3	12 min.	—	R = 0 f = 3 min. $\alpha = 60^\circ$	+2, -0 +U, -0 +10°, -0°	+3, -2 ±2 +10°, -5°	All	S ₁ + S ₂ e, f, i, j	
GMAW FCAW	B-P3-GF	12 min.	—	R = 0 f = 3 min. $\alpha = 60^\circ$	+2, -0 +U, -0 +10°, -0°	+3, -2 ±2 +10°, -5°	All	S ₁ + S ₂ a, f, i, j	
SAW	B-P3-S	20 min.	—	R = 0 f = 6 min. $\alpha = 60^\circ$	±0 +U, -0 +10°, -0°	+2, -0 ±2 +10°, -5°	F	S ₁ + S ₂ f, i, j	


Figure 3.2 (Continued)—Prequalified PJP Groove Welded Joint Details
(see 3.12) (Dimensions in Millimeters)

Single-bevel-groove weld (4)

Butt joint (B)

T-joint (T)

Corner joint (C)



ALL DIMENSIONS IN mm


Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Weld Size (E)	Notes
				Root Opening	Tolerances				
		T ₁	T ₂		Root Face	Groove Angle	As Detailed (see 3.12.3)	As Fit-Up (see 3.12.3)	
SMAW	BTC-P4	U	U	R = 0 f = 3 min. α = 45°	+2, -0 +U -0 +10°, -0°	+3, -2 ±2 +10°, -5°	All	S-3	b, e, f, g, j, k
GMAW FCAW	BTC-P4-GF	6 min.	U	R = 0 f = 3 min. α = 45°	+2, -0 +U -0 +10°, -0°	+3, -2 ±2 +10°, -5°	F, H	S	a, b, f, g, j, k
					+2, -0 +U -0 +10°, -0°	+2, -0 ±2 +10°, -5°	V, OH	S-3	
SAW	TC-P4-S	11 min.	U	R = 0 f = 6 min. α = 60°	±0 +U, -0 +10°, -0°	+2, -0 ±2 +10°, -5°	F	S	b, f, g, j, k

Double-bevel-groove weld (5)

Butt joint (B)

T-joint (T)

Corner joint (C)



ALL DIMENSIONS IN mm


Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Total Weld Size (E ₁ + E ₂)	Notes			
		T ₁	T ₂	Root Opening	Tolerances							
					Root Face	Groove Angle						
SMAW	BTC-P5	8 min.	U	R = 0 f = 3 min. $\alpha = 45^\circ$	+2, -0 +U -0 +10°, -0°	+3, -2 ±2 +10°, -5°	All	S ₁ + S ₂ -6	e, f, g, i, j, k			
GMAW FCAW	BTC-P5-GF	12 min.	U	R = 0 f = 3 min. $\alpha = 45^\circ$	+2, -0 +U -0 +10°, -0°	+3, -2 ±2 +10°, -5°	F, H	S ₁ + S ₂	a, f, g, i, j, k			
							V, OH	S ₁ + S ₂ -6				
SAW	TC-P5-S	20 min.	U	R = 0 f = 6 min. $\alpha = 60^\circ$	±0 +U, -0 +10°, -0°	+2, -0 ±2 +10°, -5°	F	S ₁ + S ₂	f, g, i, j, k			

Figure 3.2 (Continued)—Prequalified PJP Groove Welded Joint Details
(see 3.12) (Dimensions in Millimeters)

Single-U-groove weld (6)

Butt joint (B)


Corner joint (C)



ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Weld Size (E)	Notes
				Root Opening	Tolerances			
		T ₁	T ₂	Root Face	As Detailed (see 3.12.3)	Bevel Radius	As Fit-Up (see 3.12.3)	
SMAW	BC-P6	6 min.	U	R = 0 f = 1 min. r = 6 $\alpha = 45^\circ$	+2, -0 +U, -0 +6, -0 +10°, -0°	+3, -2 ± 2 ± 2	+10°, -5°	All S b, e, f, j
GMAW FCAW	BC-P6-GF	6 min.	U	R = 0 f = 3 min. r = 6 $\alpha = 20^\circ$	+2, -0 +U, -0 +6, -0 +10°, -0°	+3, -2 ± 2 ± 2	+10°, -5°	All S a, b, f, j
SAW	BC-P6-S	11 min.	U	R = 0 f = 6 min. r = 6 $\alpha = 20^\circ$	± 0 +U, -0 +6, -0 +10°, -0°	+2, -0 ± 2 ± 2	+10°, -5°	F S b, f, j

Double-U-groove weld (7)
Butt joint (B)



ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Total Weld Size (E ₁ + E ₂)	Notes			
		T ₁	T ₂	Root Opening	Tolerances							
					Root Face	Bevel Radius						
SMAW	B-P7	12 min.	—	R = 0 f = 3 min. r = 6 $\alpha = 45^\circ$	+2, -0 +U, -0 +6, -0 +10°, -0°	+3, -2 ±2 ±2 +10°, -5°	All	S ₁ + S ₂	e, f, i, j			
GMAW FCAW	B-P7-GF	12 min.	—	R = 0 f = 3 min. r = 6 $\alpha = 20^\circ$	+2, -0 +U, -0 +6, -0 +10°, -0°	+3, -2 ±2 ±2 +10°, -5°	All	S ₁ + S ₂	a, f, i, j			
SAW	B-P7-S	20 min.	—	R = 0 f = 6 min. r = 6 $\alpha = 20^\circ$	±0 +U, -0 +6, -0 +10°, -0°	+2, -0 ±2 ±2 +10°, -5°	F	S ₁ + S ₂	f, i, j			


Figure 3.2 (Continued)—Prequalified PJP Groove Welded Joint Details
(see 3.12) (Dimensions in Millimeters)

Single-J-groove weld (8)

Butt joint (B)

T-joint (T)

Corner joint (C)



ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Weld Size (E)	Notes			
		T ₁	T ₂	Root Opening							
				Root Face Bevel Radius Groove Angle	Tolerances						
SMAW	B-P8	6 min.	—	R = 0 f = 3 min. r = 10 α = 30°	+2, -0 +U, -0 +6, -0 +10°, -0°	+3, -2 ±2 ±2 +10°, -5°	All	S e, f, g, j, k			
	TC-P8	6 min.	U	R = 0 f = 3 min. r = 10 α _{oc} = 30°** α _{ic} = 45°***	+2, -0 +U, -0 +6, -0 +10°, -0° +10°, -0°	+3, -2 ±2 ±2 +10°, -5° +10°, -5°	All	S e, f, g, j, k			
GMAW FCAW	B-P8-GF	6 min.	—	R = 0 f = 3 min. r = 10 α = 30°	+2, -0 +U, -0 +6, -0 +10°, -0°	+3, -2 ±2 ±2 +10°, -5°	All	S a, f, g, j, k			
	TC-P8-GF	6 min.	U	R = 0 f = 3 min. r = 10 α _{oc} = 30°** α _{ic} = 45°***	+2, -0 +U, -0 +6, -0 +10°, -0° +10°, -0°	+3, -2 ±2 ±2 +10°, -5° +10°, -5°	All	S a, f, g, j, k			
SAW	B-P8-S	11 min.	—	R = 0 f = 6 min. r = 12 α = 20°	±0 +U, -0 +6, -0 +10°, -0°	+2, -0 ±2 ±2 +10°, -5°	F	S f, g, j, k			
	TC-P8-S	11 min.	U	R = 0 f = 6 min. r = 12 α _{oc} = 20°** α _{ic} = 45°***	±0 +U, -0 +6, -0 +10°, -0° +10°, -0°	+2, -0 ±2 ±2 +10°, -5° +10°, -5°	F	S f, g, j, k			

*α_{oc} = Outside corner groove angle.

**α_{ic} = Inside corner groove angle.


Figure 3.2 (Continued)—Prequalified PJP Groove Welded Joint Details (see 3.12) (Dimensions in Millimeters)

Double-J-groove weld (9)

Butt joint (B)

T-joint (T)

Corner joint (C)



ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Total Weld Size ($E_1 + E_2$)	Notes			
		T_1	T_2	Root Opening Root Face Bevel Radius Groove Angle	Tolerances							
					As Detailed (see 3.12.3)	As Fit-Up (see 3.12.3)						
SMAW	B-P9	12 min.	—	$R = 0$ $f = 3 \text{ min.}$ $r = 10$ $\alpha = 30^\circ$	+2, -0 +U, -0 +6, -0 +10°, -0°	+3, -2 ±2 ±2 +10°, -5°	All	$S_1 + S_2$	e, f, g, i, j, k			
	TC-P9	12 min.	U	$R = 0$ $f = 3 \text{ min.}$ $r = 10$ $\alpha_{oc} = 30^\circ*$ $\alpha_{ic} = 45^\circ**$	+2, -0 +U, -0 +6, -0 +10°, -0°	+3, -2 ±2 ±2 +10°, -5° +10°, -5°	All	$S_1 + S_2$	e, f, g, i, j, k			
GMAW FCAW	B-P9-GF	6 min.	—	$R = 0$ $f = 3 \text{ min.}$ $r = 10$ $\alpha = 30^\circ$	+2, -0 +U, -0 +6, -0 +10°, -0°	+3, -2 ±2 ±2 +10°, -5°	All	$S_1 + S_2$	a, f, g, i, j, k			
	TC-P9-GF	6 min.	U	$R = 0$ $f = 3 \text{ min.}$ $r = 10$ $\alpha_{oc} = 30^\circ*$ $\alpha_{ic} = 45^\circ**$	+2, -0 +U, -0 +6, -0 +10°, -0°	+3, -2 ±2 ±2 +10°, -5° +10°, -5°	All	$S_1 + S_2$	a, f, g, i, j, k			
SAW	B-P9-S	20 min.	—	$R = 0$ $f = 6 \text{ min.}$ $r = 12$ $\alpha = 20^\circ$	±0 +U, -0 +6, -0 +10°, -0°	+2, -0 ±2 ±2 +10°, -5°	F	$S_1 + S_2$	f, g, i, j, k			
	TC-P9-S	20 min.	U	$R = 0$ $f = 6 \text{ min.}$ $r = 12$ $\alpha_{oc} = 20^\circ*$ $\alpha_{ic} = 45^\circ**$	±0 +U, -0 +6, -0 +10°, -0°	+2, -0 ±2 ±2 +10°, -5° +10°, -5°	F	$S_1 + S_2$	f, g, i, j, k			

* α_{oc} = Outside corner groove angle.** α_{ic} = Inside corner groove angle.


**Figure 3.2 (Continued)—Prequalified PJP Groove Welded Joint Details
(see 3.12) (Dimensions in Millimeters)**

Flare-bevel-groove weld (10)

Butt joint (B)

T-joint (T)

Corner joint (C)




Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)			Groove Preparation			Allowed Welding Positions	Weld Size (E)	Notes			
		T ₁	T ₂	T ₃	Root Opening	Tolerances							
						Root Face	Bend Radius						
SMAW FCAW-S	BTC-P10	5 min.	U	T ₁ min.	R = 0 f = 5 min. $r = \frac{3T_1}{2}$ min.	+2, -0 +U, -0 +U, -0	+3, -2 +U, -2 +U, -0	All	5/16 r	e, g, j, l			
GMAW FCAW-G	BTC-P10-GF	5 min.	U	T ₁ min.	R = 0 f = 5 min. $\frac{3T_1}{2}$ min.	+2, -0 +U, -0 +U, -0	+3, -2 +U, -2 +U, -0	All	5/8 r	a, g, j, l, m			
SAW	B-P10-S	12 min.	12 min.	N/A	R = 0 f = 12 min. $\frac{3T_1}{2}$ min.	± 0 +U, -0 +U, -0	+2, -0 +U, -2 +U, -0	F	5/16 r	g, j, l, m			

Figure 3.2 (Continued)—Prequalified PJP Groove Welded Joint Details
(see 3.12) (Dimensions in Millimeters)

Flare-V-groove weld (11)

Butt joint (B)




Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Weld Size (E)	Notes			
		T_1	T_2	Root Opening Root Face Bend Radius	Tolerances							
					As Detailed (see 3.12.3)	As Fit-Up (see 3.12.3)						
SMAW FCAW-S	B-P11	5 min.	T_1 min.	$R = 0$ $f = 5$ min. $r = \frac{3T_1}{2}$ min.	+2, -0 +U, -0 +U, -0	+3, -2 +U, -2 +U, -0	All	5/8 r	e, j, l, m, n			
GMAW FCAW-G	B-P11-GF	5 min.	T_1 min.	$R = 0$ $f = 5$ min. $r = \frac{3T_1}{2}$ min.	+2, -0 +U, -0 +U, -0	+3, -2 +U, -2 +U, -0	All	3/4 r	a, j, l, m, n			
SAW	B-P11-S	12 min.	T_1 min.	$R = 0$ $f = 12$ min. $r = \frac{3T_1}{2}$ min.	± 0 +U, -0 +U, -0	+2, -0 +U, -2 +U, -0	F	1/2 r	j, l, m, n			

Figure 3.2 (Continued)—Prequalified PJP Groove Welded Joint Details
(see 3.12) (Dimensions in Millimeters)

Square-groove weld (1)

Butt joint (B)


Corner joint (C)



Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T ₁	T ₂	Root Opening	Tolerances			
SMAW	B-L1a	6 max.	—	R = T ₁	+2, -0	+6, -2	All	— e, j
	C-L1a	6 max.	U	R = T ₁	+2, -0	+6, -2	All	— e, j
FCAW GMAW	B-L1a-GF	10 max.	—	R = T ₁	+2, -0	+6, -2	All	Not required a, j

Square-groove weld (1)

Butt joint (B)



ALL DIMENSIONS IN mm


Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Gas Shielding for FCAW	Notes			
		T_1	T_2	Root Opening	Tolerances							
					As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)						
SMAW	B-L1b	6 max.	—	$R = \frac{T_1}{2}$	+2, -0	+2, -3	All	—	d, e, j			
GMAW FCAW	B-L1b-GF	10 max.	—	$R = 0$ to 3	+2, -0	+2, -3	All	Not required	a, d, j			
SAW	B-L1-S	10 max.	—	$R = 0$	±0	+2, -0	F	—	j			
SAW	B-L1a-S	16 max.	—	$R = 0$	±0	+2, -0	F	—	d, j			

Figure 3.3 (Continued)—Prequalified CJP Groove Welded Joint Details
(see 3.13) (Dimensions in Millimeters)

Square-groove weld (1)

T-joint (T)


Corner joint (C)



ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Gas Shielding for FCAW	Notes			
		T_1	T_2	Root Opening	Tolerances							
					As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)						
SMAW	TC-L1b	6 max.	U	$R = \frac{T_1}{2}$	+2, -0	+2, -3	All	—	d, e, g			
GMAW FCAW	TC-L1-GF	10 max.	U	$R = 0$ to 3	+2, -0	+2, -3	All	Not required	a, d, g			
SAW	TC-L1-S	10 max.	U	$R = 0$	±0	+2, -0	F	—	d, g			

Single-V-groove weld (2)
Butt joint (B)




Tolerances	
As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)
$R = +2, -0$	$+6, -2$
$\alpha = +10^\circ, -0^\circ$	$+10^\circ, -5^\circ$

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T_1	T_2	Root Opening	Groove Angle			
SMAW	B-U2a	U	—	$R = 6$	$\alpha = 45^\circ$	All	—	e, j
				$R = 10$	$\alpha = 30^\circ$	F, V, OH	—	e, j
				$R = 12$	$\alpha = 20^\circ$	F, V, OH	—	e, j
GMAW FCAW	B-U2a-GF	U	—	$R = 5$	$\alpha = 30^\circ$	F, V, OH	Required	a, j
				$R = 10$	$\alpha = 30^\circ$	F, V, OH	Not req.	a, j
				$R = 6$	$\alpha = 45^\circ$	F, V, OH	Not req.	a, j
SAW	B-L2a-S	50 max.	—	$R = 6$	$\alpha = 30^\circ$	F	—	j
SAW	B-U2-S	U	—	$R = 16$	$\alpha = 20^\circ$	F	—	j

Figure 3.3 (Continued)—Prequalified CJP Groove Welded Joint Details
(see 3.13) (Dimensions in Millimeters)

Single-V-groove weld (2)

Corner joint (C)




Tolerances

As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)
$R = +2, -0$	$+6, -2$
$\alpha = +10^\circ, -0^\circ$	$+10^\circ, -5^\circ$

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T_1	T_2	Root Opening	Groove Angle			
SMAW	C-U2a	U	U	R = 6	$\alpha = 45^\circ$	All	—	e, o
				R = 10	$\alpha = 30^\circ$	F, V, OH	—	e, o
				R = 12	$\alpha = 20^\circ$	F, V, OH	—	e, o
GMAW FCAW	C-U2a-GF	U	U	R = 5	$\alpha = 30^\circ$	F, V, OH	Required	a
				R = 10	$\alpha = 30^\circ$	F, V, OH	Not req.	a, o
				R = 6	$\alpha = 45^\circ$	F, V, OH	Not req.	a, o
SAW	C-L2a-S	50 max.	U	R = 6	$\alpha = 30^\circ$	F	—	o
SAW	C-U2-S	U	U	R = 16	$\alpha = 20^\circ$	F	—	o

Single-V-groove weld (2)
Butt joint (B)




ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Gas Shielding for FCAW	Notes	
		T_1	T_2	Root Opening	Tolerances				
				Root Face	Groove Angle	As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)		
SMAW	B-U2	U	—	$R = 0$ to 3 $f = 0$ to 3 $\alpha = 60^\circ$	+2, -0 +2, -0 +10°, -0°	+2, -3 Not limited +10°, -5°	All	— d, e, j	
GMAW FCAW	B-U2-GF	U	—	$R = 0$ to 3 $f = 0$ to 3 $\alpha = 60^\circ$	+2, -0 +2, -0 +10°, -0°	+2, -3 Not limited +10°, -5°	All	Not required a, d, j	
SAW	B-L2c-S	Over 12 to 25	—	$R = 0$ $f = 6$ max. $\alpha = 60^\circ$	$R = \pm 0$ $f = +0, -f$ $\alpha = +10^\circ, -0^\circ$	+2, -0 ±2 +10°, -5°	F	— d, j	
		Over 25 to 38	—	$R = 0$ $f = 12$ max. $\alpha = 60^\circ$					
		Over 38 to 50	—	$R = 0$ $f = 16$ max. $\alpha = 60^\circ$					

Figure 3.3 (Continued)—Prequalified CJP Groove Welded Joint Details
(see 3.13) (Dimensions in Millimeters)


Single-V-groove weld (2)

Corner joint (C)



Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Gas Shielding for FCAW	Notes			
		T_1	T_2	Root Opening	Tolerances							
					Root Face	Groove Angle						
SMAW	C-U2	U	U	$R = 0$ to 3 $f = 0$ to 3 $\alpha = 60^\circ$	+2, -0 +2, -0 +10°, -0°	+2, -3 Not limited +10°, -5°	All	—	d, e, g, j			
GMAW FCAW	C-U2-GF	U	U	$R = 0$ to 3 $f = 0$ to 3 $\alpha = 60^\circ$	+2, -0 +2, -0 +10°, -0°	+2, -3 Not limited +10°, -5°	All	Not required	a, d, g, j			
SAW	C-U2b-S	U	U	$R = 0$ to 3 $f = 6$ max. $\alpha = 60^\circ$	±0 +0, -6 +10°, -0°	+2, -0 ±2 +10°, -5°	F	—	d, g, j			

Double-V-groove weld (3)
Butt joint (B)



		Tolerances	
		As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)
R	± 0	$+6, -0$	
f	± 0	$+2, -0$	
α	$+10^\circ, -0^\circ$	$+10^\circ, -5^\circ$	
Spacer	SAW	± 0	$+2, -0$
	SMAW	± 0	$+3, -0$


ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T_1	T_2	Root Opening	Root Face	Groove Angle			
SMAW	B-U3a	U Spacer = $1/8 \times R$	—	$R = 6$	$f = 0$ to 3	$\alpha = 45^\circ$	All	—	d, e, h, j
				$R = 10$	$f = 0$ to 3	$\alpha = 30^\circ$	F, V, OH	—	
				$R = 12$	$f = 0$ to 3	$\alpha = 20^\circ$	F, V, OH	—	
SAW	B-U3a-S	U Spacer = $1/4 \times R$	—	$R = 16$	$f = 0$ to 6	$\alpha = 20^\circ$	F	—	d, h, j

Figure 3.3 (Continued)—Prequalified CJP Groove Welded Joint Details
(see 3.13) (Dimensions in Millimeters)

Double-V-groove weld (3)

Butt joint (B)



ALL DIMENSIONS IN mm

For B-U3c-S only

T_1	S_1
Over	to
50	60
60	80
80	90
90	100
100	120
120	140
140	160


For $T_1 > 160$ or $T_1 \leq 50$

$$S_1 = \frac{2}{3} (T_1 - 6)$$

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Gas Shielding for FCAW	Notes					
		T_1	T_2	Root Opening	Tolerances									
					Root Face	Groove Angle								
SMAW	B-U3b	U	—	$R = 0$ to 3	+2, -0	+2, -3	All	—	d, e, h, j					
GMAW FCAW	B-U3-GF			$f = 0$ to 3	+2, -0	Not limited	All	Not required	a, d, h, j					
SAW	B-U3c-S	U	—	$\alpha = \beta = 60^\circ$	+10°, -0°	+10°, -5°	F	—	d, h, j					
				$R = 0$	+2, -0	+2, -0								
				$f = 6$ min.	+6, -0	+6, -0								
				$\alpha = \beta = 60^\circ$	+10°, -0°	+10°, -5°								
To find S_1 see table above: $S_1 = T_1 - (S_2 + f)$														

Single-bevel-groove weld (4)

Butt joint (B)



ALL DIMENSIONS IN mm

Tolerances

As Detailed
(see 3.13.1)As Fit-Up
(see 3.13.1) $R = +2, -0$ $+6, -2$ $\alpha = +10^\circ, -0^\circ$ $+10^\circ, -5^\circ$


Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T_1	T_2	Root Opening	Groove Angle			
SMAW	B-U4a	U	—	$R = 6$	$\alpha = 45^\circ$	All	—	c, e, j
				$R = 10$	$\alpha = 30^\circ$	All	—	c, e, j
GMAW FCAW	B-U4a-GF	U	—	$R = 5$	$\alpha = 30^\circ$	All	Required	a, c, j
				$R = 6$	$\alpha = 45^\circ$	All	Not req.	a, c, j
				$R = 10$	$\alpha = 30^\circ$	F, H	Not req.	a, c, j
SAW	B-U4a-S	U	—	$R = 10$	$\alpha = 30^\circ$	F	—	c, j
				$R = 6$	$\alpha = 45^\circ$			

Figure 3.3 (Continued)—Prequalified CJP Groove Welded Joint Details
(see 3.13) (Dimensions in Millimeters)

Single-bevel-groove weld (4)

T-joint (T)

Corner joint (C)



Tolerances


As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)
$R = +2, -0$	$+6, -2$
$\alpha = +10^\circ, -0^\circ$	$+10^\circ, -5^\circ$

ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T ₁	T ₂	Root Opening	Groove Angle			
SMAW	TC-U4a	U	U	R = 6	$\alpha = 45^\circ$	All	—	e, g, k, o
				R = 10	$\alpha = 30^\circ$	F, V, OH	—	e, g, k, o
GMAW FCAW	TC-U4a-GF	U	U	R = 5	$\alpha = 30^\circ$	All	Required	a, g, k, o
				R = 10	$\alpha = 30^\circ$	F	Not req.	a, g, k, o
				R = 6	$\alpha = 45^\circ$	All	Not req.	a, g, k, o
SAW	TC-U4a-S	U	U	R = 10	$\alpha = 30^\circ$	F	—	g, k, o
				R = 6	$\alpha = 45^\circ$		—	g, k, o

Single-bevel-groove weld (4)

Butt joint (B)



ALL DIMENSIONS IN mm


Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Gas Shielding for FCAW	Notes			
		T ₁	T ₂	Root Opening	Tolerances							
					As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)						
SMAW	B-U4b	U	—	R = 0 to 3 f = 0 to 3 $\alpha = 45^\circ$	+2, -0 +2, -0 +10°, -0°	+2, -3 Not limited 10°, -5°	All	—	c, d, e, j			
GMAW FCAW	B-U4b-GF	U	—	R = 0 f = 6 max. $\alpha = 60^\circ$	± 0 +0, -3 +10°, -0°	+6, -0 ±2 10°, -5°	All	Not required	a, c, d, j			
SAW	B-U4b-S	U	—	R = 0 f = 6 max. $\alpha = 60^\circ$	± 0 +0, -3 +10°, -0°	+6, -0 ±2 10°, -5°	F	—	c, d, j			

Figure 3.3 (Continued)—Prequalified CJP Groove Welded Joint Details
(see 3.13) (Dimensions in Millimeters)

Single-bevel-groove weld (4)

T-joint (T)

Corner joint (C)



ALL DIMENSIONS IN mm


Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Gas Shielding for FCAW	Notes
				Root Opening	Tolerances			
		T ₁	T ₂	Root Face	As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)		
SMAW	TC-U4b	U	U	R = 0 to 3 f = 0 to 3 $\alpha = 45^\circ$	+2, -0 +2, -0 +10°, -0°	+2, -3 Not limited 10°, -5°	All	— d, e, g, j, k
GMAW FCAW	TC-U4b-GF	U	U	R = 0 f = 6 max. $\alpha = 60^\circ$	± 0 +0, -3 +10°, -0°	+6, -0 ± 2 10°, -5°	All	Not required a, d, g, j, k
SAW	TC-U4b-S	U	U	R = 0 f = 6 max. $\alpha = 60^\circ$	± 0 +0, -3 +10°, -0°	+6, -0 ± 2 10°, -5°	F	— d, g, j, k

Double-bevel-groove weld (5)

Butt joint (B)

T-joint (T)

Corner joint (C)



ALL DIMENSIONS IN mm


Tolerances	
As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)
$R = \pm 0$	+6, -0
$f = +2, -0$	± 2
$\alpha = +10^\circ, -0^\circ$	+10°, -5°
Spacer	+2, -0
	+3, -0

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T ₁	T ₂	Root Opening	Root Face	Groove Angle			
SMAW	B-U5b	U Spacer = 1/8 × R	—	R = 6	f = 0 to 3	α = 45°	All	—	c, d, e, h, j
	TC-U5a	U Spacer = 1/4 × R	U	R = 6	f = 0 to 3	α = 45°	All	—	d, e, g, h, j, k
				R = 10	f = 0 to 3	α = 30°	F, OH	—	d, e, g, h, j, k

Figure 3.3 (Continued)—Prequalified CJP Groove Welded Joint Details
(see 3.13) (Dimensions in Millimeters)

Double-bevel-groove weld (5)

Butt joint (B)




ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation		Allowed Welding Positions	Gas Shielding for FCAW	Notes
				Root Opening	Tolerances			
		T ₁	T ₂	Root Face	As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)		
SMAW	B-U5a	U	—	R = 0 to 3 f = 0 to 3 α = 45° β = 0° to 15°	+2, -0 +2, -0 α + β = +10°, -0°	+2, -3 Not limited α + β = +10°, -5°	All	— c, d, e, h, j
GMAW FCAW	B-U5-GF	U	—	R = 0 to 3 f = 0 to 3 α = 45° β = 0° to 15°	+2, -0 +2, -0 α + β = +10°, -0°	+2, -3 Not limited α + β = +10°, -5°	All	Not required a, c, d, h, j

Double-bevel-groove weld (5)

T-joint (T)

Corner joint (C)




Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation			Allowed Welding Positions	Gas Shielding for FCAW	Notes			
		T ₁	T ₂	Root Opening	Tolerances							
					Root Face	Groove Angle						
SMAW	TC-U5b	U	U	R = 0 to 3 f = 0 to 3 α = 45°	+2, -0 +2, -0 +10°, -0°	+2, -3 Not limited +10°, -5°	All	—	d, e, g, h, j, k			
GMAW FCAW	TC-U5-GF	U	U	R = 0 f = 6 max. α = 60°	±0 +0, -5 +10°, -0°	+2, -0 ±2 +10°, -5°	All	Not required	a, d, g, h, j, k			
SAW	TC-U5-S	U	U				F	—	d, g, h, j, k			

Figure 3.3 (Continued)—Prequalified CJP Groove Welded Joint Details
(see 3.13) (Dimensions in Millimeters)

Single-U-groove weld (6)

Butt joint (B)

Corner joint (C)



Tolerances


As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)
$R = +2, -0$	+2, -3
$\alpha = +10^\circ, -0^\circ$	+10°, -5°
$f = \pm 2$	Not Limited
$r = +3, -0$	+3, -0

ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation				Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T ₁	T ₂	Root Opening	Groove Angle	Root Face	Bevel Radius			
SMAW	B-U6	U	—	R = 0 to 3	$\alpha = 45^\circ$	f = 3	r = 6	All	—	d, e, j
				R = 0 to 3	$\alpha = 20^\circ$	f = 3	r = 6	F, OH	—	d, e, j
	C-U6	U	U	R = 0 to 3	$\alpha = 45^\circ$	f = 3	r = 6	All	—	d, e, g, j
				R = 0 to 3	$\alpha = 20^\circ$	f = 3	r = 6	F, OH	—	d, e, g, j
GMAW	B-U6-GF	U	—	R = 0 to 3	$\alpha = 20^\circ$	f = 3	r = 6	All	Not req.	a, d, j
	C-U6-GF	U	U	R = 0 to 3	$\alpha = 20^\circ$	f = 3	r = 6	All	Not req.	a, d, g, j

Double-U-groove weld (7)

Butt joint (B)



Tolerances


As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)
For B-U7 and B-U7-GF	
$R = +2, -0$	$+2, -3$
$\alpha = +10^\circ, -0^\circ$	$+10^\circ, -5^\circ$
$f = \pm 2, -0$	Not Limited
$r = +6, -0$	± 2
For B-U7-S	
$R = +0$	$+2, -0$
$\alpha = +10^\circ, -0^\circ$	$+10^\circ, -5^\circ$
$f = +0, -6$	± 2
$r = +6, -0$	± 2

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation				Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T_1	T_2	Root Opening	Groove Angle	Root Face	Bevel Radius			
SMAW	B-U7	U	—	$R = 0$ to 3	$\alpha = 45^\circ$	$f = 3$	$r = 6$	All	—	d, e, h, j
				$R = 0$ to 3	$\alpha = 20^\circ$	$f = 3$	$r = 6$	F, OH	—	d, e, h, j
GMAW FCAW	B-U7-GF	U	—	$R = 0$ to 3	$\alpha = 20^\circ$	$f = 3$	$r = 6$	All	Not required	a, d, h, j
SAW	B-U7-S	U	—	$R = 0$	$\alpha = 20^\circ$	$f = 6$ max.	$r = 6$	F	—	d, h, j

Figure 3.3 (Continued)—Prequalified CJP Groove Welded Joint Details
(see 3.13) (Dimensions in Millimeters)

Single-J-groove weld (8)

Butt joint (B)



ALL DIMENSIONS IN mm

Tolerances


As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)
B-U8 and B-U8-GF	
$R = +2, -0$	$+2, -3$
$\alpha = +10^\circ, -0^\circ$	$+10^\circ, -5^\circ$
$f = +3, -0$	Not Limited
$r = +6, -0$	$\pm 1/16$
B-U8-S	
$R = \pm 0$	$+3, -0$
$\alpha = +10^\circ, -0^\circ$	$+10^\circ, -5^\circ$
$f = +0, -1/8$	± 2
$r = +6, -0$	± 2

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation				Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T ₁	T ₂	Root Opening	Groove Angle	Root Face	Bevel Radius			
SMAW	B-U8	U	—	$R = 0 \text{ to } 3$	$\alpha = 45^\circ$	$f = 3$	$r = 10$	All	—	c, d, e, j
GMAW FCAW	B-U8-GF	U	—	$R = 0 \text{ to } 3$	$\alpha = 30^\circ$	$f = 3$	$r = 10$	All	Not req.	a, c, d, j
SAW	B-U8-S	U	—	$R = 0$	$\alpha = 45^\circ$	$f = 6$ max.	$r = 10$	F	—	c, d, j

Single-J-groove weld (8)

T-joint (T)

Corner joint (C)



ALL DIMENSIONS IN mm

Tolerances


As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)
TC-U8a and TC-U8a-GF	
$R = +2, -0$	$+2, -3$
$\alpha = +10^\circ, -0^\circ$	$+10^\circ, -5^\circ$
$f = +2, -0$	Not Limited
$r = +6, -0$	$\pm 1/16$
TC-U8a-S	
$R = \pm 0$	$+6, -0$
$\alpha = +10^\circ, -0^\circ$	$+10^\circ, -5^\circ$
$f = +0, -3$	± 2
$r = +6, -0$	± 2

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation				Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T_1	T_2	Root Opening	Groove Angle	Root Face	Bevel Radius			
SMAW	TC-U8a	U	U	$R = 0$ to 3	$\alpha = 45^\circ$	$f = 3$	$r = 10$	All	—	d, e, g, j, k
				$R = 0$ to 3	$\alpha = 45^\circ$	$f = 3$	$r = 10$	F, OH	—	d, e, g, j, k
GMAW FCAW	TC-U8a-GF	U	U	$R = 0$ to 3	$\alpha = 45^\circ$	$f = 3$	$r = 10$	All	Not required	a, d, g, j, k
SAW	TC-U8a-S	U	U	$R = 0$	$\alpha = 45^\circ$	$f = 6$ max.	$r = 10$	F	—	d, g, j, k

Figure 3.3 (Continued)—Prequalified CJP Groove Welded Joint Details
(see 3.13) (Dimensions in Millimeters)

Double-J-groove weld (9)

Butt joint (B)



Tolerances	
As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)
$R = +2, -0$	+2, -3
$\alpha = +10^\circ, -0^\circ$	+10°, -5°
$f = +2, -0$	Not Limited
$r = +3, -0$	±2


ALL DIMENSIONS IN mm

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation				Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T ₁	T ₂	Root Opening	Groove Angle	Root Face	Bevel Radius			
SMAW	B-U9	U	—	$R = 0 \text{ to } 3$	$\alpha = 45^\circ$	$f = 3$	$r = 10$	All	—	c, d, e, h, j
GMAW FCAW	B-U9-GF	U	—	$R = 0 \text{ to } 3$	$\alpha = 30^\circ$	$f = 3$	$r = 10$	All	Not required	a, c, d, h, j

Double-J-groove weld (9)

T-joint (T)

Corner joint (C)





ALL DIMENSIONS IN mm

Tolerances	
As Detailed (see 3.13.1)	As Fit-Up (see 3.13.1)
$R = +2, -0$	$+2, -3$
$\alpha = +10^\circ, -0^\circ$	$+10^\circ, -5^\circ$
$f = +2, -0$	Not Limited
$r = 3, -0$	± 2

Welding Process	Joint Designation	Base Metal Thickness (U = unlimited)		Groove Preparation				Allowed Welding Positions	Gas Shielding for FCAW	Notes
		T_1	T_2	Root Opening	Groove Angle	Root Face	Bevel Radius			
SMAW	TC-U9a	U	U	$R = 0$ to 3	$\alpha = 45^\circ$	$f = 3$	$r = 10$	All	—	d, e, g, h, j, k
				$R = 0$ to 3	$\alpha = 30^\circ$	$f = 3$	$r = 10$	F, OH	—	d, e, g, h, j, k
GMAW FCAW	TC-U9a-GF	U	U	$R = 0$ to 3	$\alpha = 30^\circ$	$f = 3$	$r = 10$	All	Not required	a, d, g, h, j, k

Figure 3.3 (Continued)—Prequalified CJP Groove Welded Joint Details
(see 3.13) (Dimensions in Millimeters)



Note: $90^\circ \leq \Psi \leq 170^\circ$.

**Figure 3.6—Prequalified CJP Groove, T-, and Corner Joint
(see Notes for Figures 3.2 and 3.3, Note o)**

ثبت ارزیابی روش جوشکاری

Procedure Qualification Record

- جهت اطمینان از قابل اجرا بودن و کارائی دستور العمل جوشکاری آن را مورد آزمایش قرار میدهد. در نتیجه عملاً آن را مورد اجرا قرار داده و نتایج آزمونهای انجام شده را در فرم‌های PQR ثبت می کنند. یک نمونه از فرم PQR در ضمیمه ارائه شده است.

گزارش آزمایش ارزیابی دستورالعمل جوشکاری (مخرب)

آزمایش کششی

نوع و موقعیت شکست	kg/cm ²	تنش حد نهایی (kg)	بارگذشی نهایی (kg)	سطح	ضخامت	عرض	شماره نمونه

آزمایش خمش هدایت شده

توضیحات	نتیجه	نوع خمش	شماره نمونه

بازرسی چشمی:

آزمایش پرتونگاری - فرماحتی	ظاهر جوش
شماره گزارش RT:	نتیجه:	بریدگی کناری.....
شماره گزارش UT:	نتیجه:	تخلخل حفره‌ای.....
نتایج آزمایش جوش گوش	تفتر.....
حداقل بعد چندی با سه زخم دار	حدا کثر بعد تک پاسه زخم دار	تاریخ آزمایش.....
۱	۲	گواهی کننده.....
۲	۳	آزمایش‌های دیگر

آزمایش کشش فلزجوش

مقاومت کششی (kg/cm ²)	نام جوشکار.....
مقاومت تسلیم (kg/cm ²)	تایید آزمایش توسط.....
افزایش طول در ۵ میلی متر، %
شماره آزمایش.....
شماره تأیید.....
آزمایشگاه.....

شماره آزمایش.....

هر

ما، امضاء‌کنندگان، صحت نتایج مندرج در این برگه و تطبیق آماده‌سازی، جوشکاری و آزمایش قطعات نمونه را مطابق دستورالعمل آئین نامه، تایید می‌نماییم.

سازنده یا پیمانکار.....

امضاء

معرفی به وسیله.....

عنوان.....

تاریخ.....

ارزیابی جوشکار

- برای ارزیابی جوشکار، یک جوش که دستور العمل آن مورد تأیید است، توسط جوشکار در وضعیت مورد نظر انجام می‌گیرد. از قطعه جوشکاری شده نمونه هائی اخذ شده و تحت آزمایش‌های مکانیکی تا نقطه خرابی قرار می‌گیرد. بر حسب نتایج حاصل صلاحیت جوشکار مورد ارزیابی قرار می‌گیرد. در ارزیابی جوشکار می‌توان ار نمونه های آزمایش های غیر مخرب UT و RT نیز استفاده نمود. یک نمونه از فرم ارزیابی جوشکار در ضمیمه ارائه شده است.

گزارش آزمایش ارزیابی جوشکاران، اپراتورهای جوشکاری و خال جوشکاران

نوع جوشکار

نام:

شما و شناسنامه: **نام:**

يشتمل دسته العمل، هوشکاری، اصلاح، تاریخ

ثبت مقادیر واقعی مورد استفاده در ارزیابی	محدوده ارزیابی	متغیرها نوع اروش
		الکترود (تک یا چندگانه)
		جریان / قطبیت
		موقعیت
		موقعیت جوشکاری
		پشت بند (بله، خیر)
		نوع مصالح
		مصالح پایه
		شیاری ضخامت (ورق) گوشه
		شیاری ضخامت (لوله) گوشه
		شیاری قطر (لوله) گوشه
		مصالح پرکننده
		شمارة مشخصه
		ردیف
		نوع گذازآور / گاز
		سایر موارد

ضرورت بازررسی

- برای حصول یک جوش خوب باید پنج عامل زیر را برآورده نمود. (قانون پنج P)
 - روش جوشکاری (*Process selection*)
 - آماده سازی مناسب لبه ها (*Preparation*)
 - دستورالعمل جوشکاری (*Procedure*)
 - پرسنل جوش (*Personnel*)
 - بازررسی و تأیید جوش (*Prove*)
- چهار دستورالعمل اول در ردۀ بازررسی های تضمین کیفیت بازررسی های کنترل کیفیت "Q/C" (Quality Control) و قانون پنجم در ردۀ بازررسی های تضمین کیفیت "Q/A" (Quality Assurance) می باشد.

خصوصیت بازرس

- 1- بازرسین فنی بایستی با نقشه های مهندسی آشنایی کامل داشته و نقشه را خوب خوانده و بفهمد.
- 2- اصطلاحات تعریف شده بین المللی ، علائم جوشکاری و کدهای استاندارد را بدانند.
- 3- از فرآیندهای جوشکاری اطلاعات کافی داشته باشند.
- 4- با روش های تست استاندارد آشنا باشند.
- 5- توانائی آزمایش تأیید صلاحیت جوشکاری را داشته باشند.
- 6- اطلاعات کافی از متالورژی جوش داشته باشند ، تا در هنگام ضرورت قادر به تجزیه و تحلیل مسائل مهندسی جوش باشند.
- 7- در جوش تجربه داشته و عیوب جوش را بشناسند و روش های پیشگیری یا رفع آنها را بدانند.
- 8- در کار بازرسی ، تجربه آموخته باشند.
- 9- گزارشات کنترل کیفیت را در مراحل مختلف ساخت ، تهیه و ثبت نمایند.
- 10- در تمامی مراحل ساخت پروژه ، حضور داشته باشند.

وظایف بازرس جوش

- تفسیر نقشه های جوشکاری و مشخصات آنها.
- بررسی سفارش خرید به منظور حصول اطمینان از درستی تعیین مواد جوشکاری و مواد مصرفی.
- بررسی و شناسایی مواد دریافت شده طبق مشخصات سفارش خرید.
- بررسی ترکیبات شیمیایی و خواص مکانیکی از روی گزارش بورد طبق نیازمندیهای معین شده.
- بررسی فلز مبنا از نظر عیوب و انحرافات مجاز.
- بررسی نحوه انبار کردن فلز پر کننده و دیگر مواد مصرفی.
- بررسی تجهیزات مورد استفاده.
- بررسی آماده سازی اتصال جوش.
- بررسی جفت و جوری اتصال.
- بررسی به کار گرفتن دستورالعمل جوشکاری تایید شده.
- بررسی ارزیابی صلاحیت جوشکاران و اپراتورهای جوشکاری.
- انتخاب نمونه های آزمایش تولید.
- ارزیابی نتایج آزمایش.
- نگهداری سوابق.
- تهیه و تنظیم گزارش.

مراحل بازرسی عینی جوش

"Visual inspection"

- بازرسی عینی قبل از جوشکاری
- بازرسی عینی هنگام جوشکاری
- بازرسی عینی بعد از جوشکاری

- بازرسی عینی قبل از جوشکاری شامل مواردی می باشد که عبارتند از
- A. اطلاع از کیفیت مورد نظر کار و میزان حسابیت سازه
 - B. مطالعة دقیق نقشه ها و مشخصات فنی
 - C. مقایسه مشخصه داده شده توسط مشتری و کیفیت مورد نیاز با محصول
 - D. مطالعة استانداردهای مربوطه و انتخاب استانداردهای اجرائی
 - E. انتخاب و ارزیابی روش جوشکاری
 - F. انتخاب مصالح و بازرسی مصالح
 - G. انتخاب مواد مصرفی و بازرسی مواد مصرفی

در انتخاب الکترود دو مطلب باید در نظر گرفته شود :

1) نوع الکترود

در خصوص نوع الکترود مسائل موردنظر عبارتند از :

جنس قطعه و ضخامت آن

نوع تنش و مقدار تنش

درجه حرارت

خورنده‌گی محیط

نوع جریان الکتریکی وضعیت جوشکاری

نرخ رسوب

سهولت کار

قیمت الکترود

در خصوص سایز الکترود باید به موارد زیر توجه کرد :

ضخامت قطعه

طرح اتصال

وضعیت جوشکاری

سهولت کار

کیفیت جوش

هزینه

بازرسی مواد مصرفی جوش توسط بازرس می‌تواند به دو صورت انجام گیرد :

1- انجام آزمایش بر روی خواص جوش الکترود و یا پودر و مفتول مصرفی جوش

2- اخذ گواهی از شرکت های سازنده الکترود ، پودر یا مفتول جوشکاری

بازرسی ورق های مصرفی

- در صورت مشاهده ترک های ناشی از تورق و یا ناپیوستگی های سطحی می توان مطابق جدول زیر به تعمیر و عملیات اصلاحی اقدام نمود.
- در مواردی که سطح ورق ها دارای ناپیوستگی های با عمق زیاد و یا سوراخ باشد و نیاز به این باشد که با جوش پر شود ، بهتر است اولاً این مواد با الکترودهایی کم هیدروژن مثل E7018 اصلاح شوند ، ثانیاً پس از جوشکاری با آزمایش های PT یا MT از کیفیت کامل موضع جوشکاری شده اطمینان حاصل نمود.

شرح ناپیوستگی	تعییر لازم
هر نوع ناپیوستگی با طول مساوی 25 میلیمتر یا کمتر	لازم نیست
هر نوع ناپیوستگی با طول بزرگتر از 25 میلیمتر و عمق کمتر از 3 میلیمتر	لازم نیست ولی عمق باید مورد بررسی قرار گیرد
هر نوع ناپیوستگی با طول بزرگتر از 25 میلیمتر و عمق 3 تا 6 میلیمتر	باید کاملاً برداشته ولی جوش لازم نیست
هر نوع ناپیوستگی با طول بزرگتر از 25 میلیمتر و عمق بیش از 6 میلیمتر	باید کاملاً برداشته و با جوش پر شود

H. بازرسی و سایل و تجهیزات جوشکاری ، پرشکاری و عملیات حرارتی

I. طرح و تنظیم و یا ارائه دستورالعمل جوشکاری

موارد مهمی که در دستورالعمل جوشکاری (WPS) بایستی به آن اشاره شود عبارتند از نوع فرآیند جوشکاری ، نوع ضخامت ورق مصرفی ، نوع و قطر الکترود مصرفی ، مشخصات الکتریکی دستگاه جوش و اتصال الکترود ، ترتیب جوشکاری ، نحوه تکنیک جوشکاری ، عملیات حرارتی پیش گرم و یا پس گرم کردن.

تست هایی که در گزارش کیفیت دستورالعمل جوش (PQR) بکار برده می شوند و معمولاً در استاندارد نیز به آنها توجه شده است شامل :

بازرسی چشمی

آزمایش غیر مخرب ، Pt یا Mt و Ut یا Rt

آزمایش کشش عرضی

آزمایش خمس

آزمایش ضربه در شرایط خاص یا به تشخیص بازرس.

J. آزمون جوشکاران و اپراتورها و بررسی صلاحیت آنها

ممولاً در صورت تست در حالت گوشه علاوه بر کنترل چشمی ظاهر جوش ، آزمایش شکست نمونه جوش گوشه انجام می شود و در صورت جوشکاری در حالت نفوذی و اتصال لب به لب علاوه بر کنترل چشمی آزمایش خمس و یا آزمایش غیر مخرب Ut یا Rt انجام می شود.

K. بررسی تسهیلات آزمایش

بازرسی عینی نر حین جوشکاری شامل مواردی می باشد که عبارتند از

- A. بازرسی قطعات متصل شونده و درزهای آماده جوشکاری
- B. بازرسی محل های جوش و سطوح مجاور به منظور اطمینان از تمیزی و عدم آلودگی با موادی که اثرات زیان بخشی بر جوش دارند
- C. بازرسی سطوح جوشکاری شده با شعله یا شیار زده ، از نظر پوسته ، ترک و غیره
- D. بازرسی و ترتیب و توالی جوشکاری ، استفاده از قیدها ، گیره ها و سایر تمهیدات به منظور کنترل پیچیدگی ناشی از جوشکاری
- E. بازرسی مواد مصرفی جوشکاری از نظر دارابودن شرایط مطلوب و گرم و خشک کردن الکترودهای روپوش قلیایی طبق دستورالعمل های مصوبه
- F. بازرسی جوشکارانی که تایید صلاحیت شده اند و کد دارند و کنترل کیفیت جوش آنها در حین کار
- G. کنترل تمیز کاری و حذف سرباره های جوش در بین لایه و پاس های جوشکاری
- H. بازرسی پیش گرم کردن و حفظ درجه حرارت بین پاسی در صورت لزوم

نوع الكترود	ستون (الف)	ستون (ب)
E70xx	4 ساعت	بين 4 تا 10 ساعت
E70xxR	9 ساعت	بين 4 تا 10 ساعت
E70xxHZR	9 ساعت	بين 4 تا 10 ساعت
E7018M	9 ساعت	بين 4 تا 10 ساعت
E70xx.x	4 ساعت	بين 4 تا 10 ساعت
E80xx.x	2 ساعت	2 تا 10 ساعت
E90xx.x	1 ساعت	1 تا 5 ساعت
E100xx.x	0.5 ساعت	0.5 تا 4 ساعت

بازرسی عینی بعدازجوشکاری شامل مواردی می

باشد که عبارتند از

- A. بازرسی چشمی از نظر وجود عیوبی نظیر
- تخلخل ظاهری
- عدم امتراج کامل
- عدم نفوذ کامل جوش
- بریدگی پای جوش
- لوچه

• ترکهای سطحی

• گردئه بیش از حد جوش

- B. بازرسی ابعاد جوش و قطعه جوشکاری شده از نظر
- ظاهر نهائی جوش
- اندازه نهائی جوش
- طول جوش

C. بازرسی تغییر شکل‌های ناشی از جوشکاری نظیر:

- انقباض موضعی

- خیز

- خمشگی

- تابیدگی

- چرخش

- کمانش

- موجودار شدن و غیره

- شکستگی محور

- بهم خوردگی زاویه ها و غیره

D. بازرسی تنش زدائی و سختی سنجی پس از تنش زدائی

-

E. بازرسی های غیر مخرب نظیر:

-

- پرتونگاری

- امواج مافوق صوت

- عیب یابی ذره مغناطیسی

- مایع نافذ

- جریان گردابی و غیره

چک لیست بازرسی عینی جوش

• نکاتی که قبل، حین و بعد از جوشکاری باید مورد بازرسی عینی تهرارگیرند

• ۰۰۰ کنترل قبل از جوشکاری

• ۰۰۰ کنترل در حین جوشکاری




• ۰۰۰ کنترل بعد از جوشکاری

1-زاویه پخی " Included angle "


زاویه پخی باید به اندازه ای باشد که الکترود به راحتی به ریشه جوش برسد و در عبورهای متوالی ،از ذوب کامل جداره ها اطمینان حاصل گردد.در حالت عمومی هرچه این زاویه بزرگتر باشد، مصلاح جوش افزایش می یابد.

2-دهانه ریشه " Root opening "


در صورت عدم استفاده از تسمه پشت بند، امکان سوختن ریشه در عبور (پاس) اول وجود دارد.در نتیجه در این حالت دهانه ریشه قدری کاهش داده می شود.در صورتی که امکان سنگ زدن ریشه از پشت کار وجود داشته باشد، عدم ذوب کامل ریشه در پاس اول خیلی جدی نیست.در صورت استفاده از تسمه پشت بند، دهانه ریشه افزایش داده می شود تا ذوب کامل ریشه و تسمه پشت بند امکان پذیر باشد.در این حالت نیازی به سنگ زدن ریشه از پشت کار نمی باشد و امکان سوختن ریشه نیز در میان نیست.در پخی دو طرفه، تسمه فاصله دهنده نقش ورق پشت را بازی میکند، لیکن قبل از جوش پشت کار باید سنگ زده و برداشته شود.




3 ضخامت ریشه "Root face"



- رعایت ضخامت ریشه به منظور جلوگیری از سوختن ریشه می باشد و معمولاً در جوشاهای اتوماتیک زیرپودری مقرر میگردد. ضخامت ریشه دارای یک مقدار حداقل و یک مقدار حداکثر است و در صورت عدم رعایت مقدار حداقل، ریشه جوش می سوزد، و در صورت عدم رعایت مقدار حداکثر، ذوب ریشه کامل نخواهد بود.



(ب) ضخامت ریشه مناسب باعث نفوذ کامل می شود




(ب) ضخامت ریشه زیاد باعث عدم نفوذ کامل می شود



(الف) ضخامت ریشه کم باعث سوختن ریشه می شود

●●● " Alignment " 4-هم محوری درز



- عدم هم محوری صحیح باعث تشکیل قسمتهایی با نفوذ ناقص میشود.

●●● " Cleanliness of joint " 5-تمیزی درز

- سطوح درز باید تمیز و عاری از هر گونه آلودگی، گرد و غبار و رطوبت باشد.

●●● " Proper type & size of electrode " 6-نوع و اندازه مناسب الکترود

●●● " electrode " 6-نوع و اندازه الکترود

- نوع و اندازه الکترود باید برای نوع فلز مورد جوش، وضعیت جوشکاری، وظیفه جوش، ضخامت ورق، اندازه درز وغیره مناسب باشد.

●●● " Proper welding current & polarity " 7-قطبیت و شدت جریان مناسب

●●● " polarity " 7-قطبیت و شدت جریان مناسب


- بر حسب نوع و قطر الکترود، نوع درز و وضعیت جوشکاری باید شدت جریان و قطبیت جوشکاری مناسب باشد.

●●● " proper tack weld " 8-خل جوش مناسب

- خال جوشها باید کوچک و بلند باشند، به طوری که با جوش اصلی تداخل نداشته باشند. در ورقهای ضخیم، برای اجرای خال جوشها باید از الکترودهای کم هیدروژن استفاده نمود.

• ٩-ذوب خوب " Good fusion "

هر پاس جوش باید بطور کامل با ورق پشت بند، عبور قبلی و فلز پایه هم جوش شده و امتزاج کامل بوجود آورد، بطوریکه هیچ گونه حفره هوا در فصل مشترک بوجود نیاید.



• ١٠- پیش گرمایش و درجه حرارت بین پاسی " Proper preheat & interpass temperature "

مقدار پیش گرمایش و درجه حرارت مناسب برای عبور های میانی، بستگی به ضخامت ورق، نوع فولاد، روش جوشکاری و درجه حرارت محیط دارد. در صورتیکه شرایط گفته شده، پیش گرمایش و درجه حرارت خاصی برای جوش های میانی لازم بدارند، در حین عملیات جوشکاری این موضوع باید به طور پیوسته مورد بررسی قرار گیرد.

•

11. توالی و ترتیب پاسهای جوش " Proper sequencing of passes "




(الف) هرج مشكلی برای عبور
بسیار وجود ندارد




(ب) به علت فشار محدود امکان
تولید حفرات هوا وجود ندارد

- ترتیب و توالی پاسها باید طوری باشد که امکان وقوع حفرات هوا در حد فاصل عبورهای جوش وجود نداشته باشد.


12. سرعت مناسب حرکت نوک الکترود " Proper travel speed "




- اگر سرعت حرکت الکترود خیلی آهسته باشد، فلز جوش ذوب شده و گل جوشکاری، به سمت جلوی الکترود فرار کرده و شروع به سرد شدن می نماید. بر نتیجه جوش اصلی که به روی این قسمت اجرا میگردد، شانس نفوذ کافی به ریشه را از دست می دهد.



- اگر سرعت حرکت الکترود افزایش داده شود، امکان فرار مواد مذاب به جلوی الکترود وجود نداشته و نفوذ کامل صورت میگیرد.
- 13. لوجه جوش "Over lap "





- اگر سرعت نوک الکترود خیلی آهسته باشد، مقادیر زیادی از فلز جوش در حال رسوب، از لبه های نوار جوش به سمت بیرون سرریز (شره) کرده وهم جوشی کامل بوجود نمی آید. عمل سرریز به سهولت در حین جوشکاری قابل مشاهده بوده و روش اصلاح آن افزایش سرعت جوشکاری است.



• ۱۴. غلتاندن حوضچه مذاب نوک الکترود در جوشهای سر بالا (قائم) ○○○

" Tilt of crater in vertical welding "



●●● "Filled crater" چاله انتهای جوش


• چاله دو انتهای جوش از دو نقطه نظر زیر ممکن است بحث انگیز باشد:
• ضخامت گلوی موثر جوش کمتر از سایر قسمتها ای نوار جوش است.

• با توجه به اینکه سطح مقعری دارند، امکان وقوع ترک ستاره ای در آنها در هنگام سرد شدن وجود دارد. در جوش‌های گوشه پیوسته، خطر چاله جوش وجود ندارد، زیرا جوشکاری در هنگام تعویض الکترود، چاله انتهای جوش قبلی را با جوش پر می‌کند.

• در جوشها با طول محدود، لازم است انتهای جوش در محلی واقع گردد که میزان تنش کم است، در غیر اینصورت باید دقت گردد که در انتهای جوش چاله کاملاً "پر شود".


• مثال: در جوش گوشه ورق فوقانی اتصال صلب به بال تیر، در شروع و ختم جوش باید دقیق بود تا چاله ایجاد نشود.

• مثال: در جوش نبشی نشیمن، جوش از پشت بال نبشی شروع شده و به لبه آن ختم می‌گردد. بطوریکه چاله در این محل که تنش های کمتری دارد، ایجاد شود.



انتهای جوش
(چاله جوش بحرانی نیست)


• مثال: در جوشهای منقطع، تشکیل چاله در دو انتهای هر قطعه، مشکل مهمی نیست، لیکن با روش کار مناسب نباید اجازه تشکیل آن را بدheim. بگث جوشکار در انتهای وکمی برگشت دست به عقب مشکل را حل مینماید.




برکردن چاله انتهایی ترک ستاره ای
محل چاله انتهایی ترک ستاره ای و وقوع
ترک ستاره ای
را از بین می برد

16. بریدگی لبه های جوش "Under cut "


الف: قوس الکتریکی قادر به ذوب قسمتهایی از فلز پایه می باشد




- ب: اگر طول قوس بلند باشد (فاصله نوک الکترود تا سطح جوش)، مصالح جوش نمی توانند تمام فضای جوش ذوب شده را پر کند، در نتیجه در لبه جوش گود افتادگی یا بریدگی بوجود می آید.





پ: با کاهش طول قوس، مصالح جوش تمام فضای ذوب شده را پر می کند.



- با توجه به اینکه بریدگی به راحتی با اصلاح دستور العمل جوشکاری قابل اصلاح است، وقوع آن قابل پذیرش نیست. اما این سؤال پیش می آید که بریدگی در چه مواردی مضر بوده و باید اصلاح گردد.
- 1- اگر بریدگی باعث کاهش عمدہ در ضخامت یا سطح مقطع گردد، وقوع آن مردود است.




• اگر تنش در امتداد عرضی اعمال گردد، بریدگی همانند یک زخم عمل کرده وزیانبار خواهد بود.




طبق آیین نامه AWS ، در حالتی که نیرو بطور عرضی بر بریدگی اعمال می گردد، بریدگی تا عمق 0.25 میلیمتر و در صورتیکه نیرو به موازات بریدگی باشد، تا عمق 0.8 میلیمتر قابل قبول است.

به عنوان آخرین مطلب، توجه گردد که بریدگی تحتانی دارای تأثیر زیانبارتری نسبت به بریدگی فوقانی است.




هر گونه برون محوری، باعث ایجاد تنش خمشی در بریدگی تحتانی می گردد.



• ۱۷. گرده در جوش‌های شیلری ۰۰۰





Slight Reinforcement on Groove welds •

- وجود گرده تا ۱.۵ میلیمتر در جوش‌های شیلری قابل پذیرش است. مقادیر بیشتر باعث افزایش مخارج و کاهش مقاومت خستگی می‌گردد.




• ۰۰۰ "Full size of fillet weld" ۱۸

با استفاده از اندازه گیری‌های مخصوص، اندازه جوش گوشه باید کنترل گردد.



(الف) مناسب برای روش تخت



(ب) مناسب برای روش محدب

• 19. وقوع ترک "Cracks"

- وقوع هر نوع ترک به هر صورت (سطحی یا عمیق)، باعث مردود شدن جوش خواهد شد.

- **4. Inspection of Welding**
- *Observation of welding operations and visual inspection of in-process and completed welds shall be the primary method to confirm that the materials, procedures and workmanship are in conformance with the construction documents. For structural steel, all provisions of AWS D1.1/D1.1M Structural Welding Code—Steel for statically loaded structures shall apply.*
- *As a minimum, welding inspection tasks shall be in accordance with Tables N5.4- 1, N5.4-2 and N5.4-3. In these tables, the inspection tasks are as follows:*
- ***O – Observe these items on a random basis. Operations need not be delayed pending these inspections.***
- ***P – Perform these tasks for each welded joint or member***

TABLE N5.4-1
Inspection Tasks Prior to Welding

Inspection Tasks Prior to Welding	QC	QA
Welding procedure specifications (WPSs) available	P	P
Manufacturer certifications for welding consumables available	P	P
Material identification (type/grade)	O	O
Welder identification system ¹	O	O
Fit-up of groove welds (including joint geometry) <ul style="list-style-type: none"> • Joint preparation • Dimensions (alignment, root opening, root face, bevel) • Cleanliness (condition of steel surfaces) • Tacking (tack weld quality and location) • Backing type and fit (if applicable) 	O	O
Configuration and finish of access holes	O	O
Fit-up of fillet welds <ul style="list-style-type: none"> • Dimensions (alignment, gaps at root) • Cleanliness (condition of steel surfaces) • Tacking (tack weld quality and location) 	O	O
Check welding equipment	O	—

¹ The fabricator or erector, as applicable, shall maintain a system by which a welder who has welded a joint or member can be identified. Stamps, if used, shall be the low-stress type.

TABLE N5.4-2
Inspection Tasks During Welding

Inspection Tasks During Welding	QC	QA
Use of qualified welders	○	○
Control and handling of welding consumables <ul style="list-style-type: none"> • Packaging • Exposure control 	○	○
No welding over cracked tack welds	○	○
Environmental conditions <ul style="list-style-type: none"> • Wind speed within limits • Precipitation and temperature 	○	○
WPS followed <ul style="list-style-type: none"> • Settings on welding equipment • Travel speed • Selected welding materials • Shielding gas type/flow rate • Preheat applied • Interpass temperature maintained (min./max.) • Proper position (F, V, H, OH) 	○	○
Welding techniques <ul style="list-style-type: none"> • Interpass and final cleaning • Each pass within profile limitations • Each pass meets quality requirements 	○	○

TABLE N5.4-3

Inspection Tasks After Welding

Inspection Tasks After Welding	QC	QA
Welds cleaned	O	O
Size, length and location of welds	P	P
Welds meet visual acceptance criteria <ul style="list-style-type: none"> • Crack prohibition • Weld/base-metal fusion • Crater cross section • Weld profiles • Weld size • Undercut • Porosity 	P	P
Arc strikes	P	P
<i>k</i> -area ¹	P	P
Backing removed and weld tabs removed (if required)	P	P
Repair activities	P	P
Document acceptance or rejection of welded joint or member	P	P

¹ When welding of doubler plates, continuity plates or stiffeners has been performed in the *k*-area, visually inspect the web *k*-area for cracks within 3 in. (75 mm) of the weld.